

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 6 Page(s) 2274-75)

Set ¼ Sec. post from which
 A Fir, 10" dia., bears N.54°E., 90 lks.
 A Fir, 6" dia., bears S.31°W., 83 lks.

Douglas Co. Surveyors Office - Arthur Boyer - J.H. Wittmeyer & Chas. Neal, Witnesses - Dec. 30 1937 and Jan. 1938 - "Old" Vol 1, renewed corners & C.S. File 30/52

Set from orig. stump which shows scribe mark (to SW) set 3"x3" post from which:
 24" D.Fir, bears S.67°E., 25.4 ft.
 10" W.Fir, bears S.77°W., 40.4 ft.

Wilford Haines - For: Jim Whipple - Dec. 1962 - M 24-42

Found - 24" Fir stump S.67°E., 25.4 ft.
 10" Fir, S.77°W., 40.4 ft., down.
Set - 1"x1"x36" T-iron.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - Feb/March 1963 - C.S. File 53/9-11

Found - Haines "T" iron cap at corner.
 16" D.Fir, not White Fir, S.77°W., 40.4 ft., recently uprooted and down.
 30" D.Fir stump S.67°E., 25.4 ft., found portion of scribe mark.
 Rotten remnants of Fir stumps to NE & SW, no marks remaining.
DID NOT SET NEW MONUMENT, BRASS CAP.
New BTs- 14" D.Fir, S.68°W., 90.7 ft., mkd: ¼ S9 CS BT.
 6" D.Fir, S.59°E., 59.2 ft., mkd: ¼ S10 CS BT.
Corner lies in recently bulldozed fire trail. A fence corner (fences East & South) bears South 125 ft.

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor & Robert Browning, Surveying Technician under Group #1955, surveyed 2000/2001 (DCSO rec. Vol. 54 pg(s) 20854-5)

The ¼ sec. cor. of secs. 9 & 10, perpetuated from original evidence no longer in existence by Boyer, in 1937, further perpetuated by Haines, in 1962, further perpetuated by Godfrey, in 1963, monumented with a 1x1". "T" shaped iron rod, firmly set, projecting 4" above the ground, from which the remains of BTs mkd. by Boyer continued next page

