

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 6 Page(s) 2273)

Set ¼ sec. post, from which
A Fir 4" dia., bears S.83°W., 33 lks. dist.
A Fir 15" dia., bears N.5°W., 18 lks. dist.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #658 dated May 21, 1896 (DCSO records Vol. 6 Page(s) 2318 and Page 3079)

Qr. sec. cor., which is a Hemlock post 3" sq., 24" above ground, marked and witnessed as described by the surveyor general.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 6 Page(s) 2319)

At the ¼ sec. cor. on the S. bdy. of sec.34; the post, and bearing tree described by the surveyor general as a fir, 4" dia., bearing S.83°W., 33 lks. dist., are entirely destroyed. I re-establish this ¼ sec. cor. from the bearing tree on the N., as follows:
Set a Fir post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor., marked ¼ S on N. face; from which
A Fir 12" dia., bears S.42°W., 64 lks. dist. mkd. ¼ S BT.
A Fir 15" dia., bears N.5°W., 18 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Mike Stone - April 1963 - C.S. File 53/9-129

Found - 32" Fir S.42°W., 42.2 ft., has been previously opened, good scribing "¼S" visible on old face. Old Fir stump N.5°W., 11.9 ft., small portion of old face exposed, good scribing, portion of "4" visible.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 4 W
S ¼ S34
T 24 S
1963

New BTs- 32" Red Cedar N.81°E., 21.0 ft. mkd. ¼ S34 CSBT.
24" Hemlock N.77°W., 53.3 ft. mkd. ¼ S34 CS BT.
Corner lies in dry draw draining SW.

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2168, Surveyed May/Nov. 2007 - DCSO records Vol. 57 Pages 22584-5

The ¼ sec. cor. of sec. 34 only on the S. bdy. of the Tp., remonumented by Godfrey, in 1963, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd.

from which the remains of an orig. bearing tree

A sawed fir stump, 26" dia., bears N.0¼°E., 11.9 ft., with a healed double blaze. (Record, N.5°W.)

and remains of a bearing tree mkd. by Nicklin and Chapman

A sawed, tin-capped fir stump, 32" dia., bears S.42°W., 42.2 ft., with no marks visible.

and remains of a bearing tree mkd. by Godfrey

A cedar, 41" dia., bears N.81°E., 20.1 ft., with a healed double blaze.

and new bearing tree

A fir, 59" dia., bears N.51½°W., 104.4 ft., mkd. ¼ S34 BT.