

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - William P. Wright, Deputy Surveyor, under Contract No. 514, dated Aug. 27, 1884 (DCSO records Vol. 6 Page(s) 2299)</p> <p>-----</p> <p>Set post 4" dia., 4 ft. long, with marked stone 12" in ground for 1/4 sec. cor. mkd: 1/4 S on N face, from which A Chinquapin, 12" dia., bears N.87°E., 55 lks. A Fir, 40" dia., bears N.67°E., 82 lks.</p>
<p>Wilford N. Haines - Approx. 1960 filed 12/1965 - C.S. File 54/16-23C</p> <p>-----</p> <p>Set - 36" T-iron with cap Scribed- 8" D.Fir, N.58°E., 20.6 ft.</p>
<p>Douglas Co. Surveyors Office - March 15, 1960 - C.S. File 49/42-50</p> <p>-----</p> <p>Found - Orig. 40", now 48" Fir, N.67°E. 54.1 ft. shows orig. bark scribing "1/4S" also new bark scribing "1/4S". Orig. Chinquapin BT now a snag. 6" R.Fir, new scribing bears N.57°E., 20.9 ft. Find also, Haines angle iron & cap at corner. <u>I do not set Brass cap at Corner.</u> New BT - 16" R.Fir, bears S.41 1/2°E., 46.1' scribed S34 CS BT Note - This corner probably renewed by Haines with in the past year but not recorded.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Stone - Jerry Layne - Nov. 1965 - C.S. File 54/16-35</p> <p>-----</p> <p>Found - Haines' T-iron, as recorded in 1960. All BTs down & dead. New BTs- 18" D.Fir, N.3°W., 27.9 ft. mkd: 1/4 S27 CS BT. 18" Maple, S.29°W., 34.3 ft. mkd: 1/4 S34 CS BT. Note - This corner lies on rolling North slope, changing to very steep.</p>
<p>BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41 Page(s) 16146-47)</p> <p>-----</p> <p>The 1/4 sec. cor. of secs. 27 & 34, perpetuated and recorded by Haines in 1959, from orig. evidence no longer in existence, and further perpetuated by Byron in 1960, and further perpetuated by Tracy in 1965, monumented with a 1" "T" shaped iron rod, firmly set, projecting 10" above ground, from which the remains of a bearing tree mkd. by Haines: (Cont.)</p>

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Corner Secs 27 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A Fir stump, 8" dia., bears N.55 3/4°E., 32 lks., with fragmentary scribe marks visible on open blaze. and the remains of a bearing tree mkd. by Byron:
A root hole, bears S.41½°E., 70 lks., with a down fir alongside, 18" dia., with fragmentary scribe marks visible on open blaze. and bearing trees mkd. by Tracy:
A Fir, 24" dia., bears N.5½°W., 41½ lks., with healed blaze.
A Maple, 24" dia., bears S.26½°W., 52 lks., with scribe marks ¼ S34 CS BT visible on open blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
¼ $\frac{S\ 27}{S34}$
T23S R4W
1976
Reset "T" shaped iron rod alongside iron post.

Fd. 1/1995 M 121-69

Daniel A Renton, Minister-Glaeser Surveying - Garrett Finch & Crew - For: US Department of Interior, BLM - Great Expectation & Fast Lane -Task B -Jan 18,2023 - M178-72 A-F

Found - 3¼" BLM brass cap (properly mkd) 0.4 ft above ground in good condition with a 1" Haines brass cap to the north and alongside from which:
22" Maple bears S.26°W., 33.3 ft to side center, with scabbed blaze & location poster (1965)
35" Fir bears N.4°W., 27.1 ft to side center, scabbed blaze with BT sign (1965)
24" rotten stump (2 ft high) bears N.54°E., 28.2 ft to center of stump (1960)
Set chaining nail at side center, BT signs on front and rear, and painted red band for existing BTs