

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 6 Page(s) 2271)

-
- Set post cor. of secs. 1, 6, 7 and 12, from which
- A Fir 8" dia., bears N.32°W., 47 lks. dist.
 - A Cedar 12" dia., bears N.5°E., 47 lks. dist.
 - A Cedar 20" dia., bears S.28°E., 40 lks. dist.
 - A Cedar 8" dia., bears S.35°W., 53 lks. dist.

Herbert R Jones, PE - For: Weyerhaeuser Timber Co. & Camac Veneer Inc. - 7/1959 (DOWNLOADED FROM LANE CO. WEBSITE, FILED W/DCSO & ADDED 4/13/2023) -C.S. File 65/111-42

-
- Found - 2"x2"x3' post and the following trees referenced by the Weyerhaeuser method:
- *12" Fir S.28°W., 23.3 ft.
 - *60" Fir S.66°E., 3.1 ft. *BEARINGS 180° OFF
 - *10" Fir N.9°E., 10.2 ft. SEE 2016 LCSO CORNER REPORT*
 - *60" Fir N.85°W., 8.8 ft.
- OBTs - Remains of Cedar, S.28°E., 40 lks. This tree has been chopped out. Part of the reverse scribe is visible on chopped out slab. This tree now a dead and down windfall.
- Remains of Cedar, S.35°W., 53 lks. This tree has been chopped out. Part of the reverse scribe is visible on chunks left on ground. This tree now a dead and down windfall.
- Remains of 80" Fir, N.32°W., 47 lks. This is now an 80" fir stub. This tree shows very old cruisers marks but no scribe visible.
- Set - 1/2" galvanized pipe at proper position for corner. Weyerhaeuser alum. tags & W nails were already set in proper locations.

Fd. stake & 3 old BTs - W. Haines 11/1963 - M26-80

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 1965 - C.S. File 54/16-20

-
- Found - 2" x 2" sq. post and BTs as follows:
- Orig. 8" now 60" Fir N.32°W., 31.0 ft., shows old fragmentary bark scribe.
 - Orig. 20" now 24" Cedar S.28°E., 26.4 ft., down and out of place.
 - Orig. 8" now 20" Cedar S.35°W., 35.0 ft., down, find reverse scribe previously removed from BT.
- No trace of NE. BT. Continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12; 6 & 7, T23-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S
R4W S 1 | S 6 R3W
S 12 | S 7
1965

New BTs- 12" D.Fir S.9°W., 10.2 ft. mkd. T23S R4W S12 DCS BT
9" D.Fir S.60°E., 60.0 ft. mkd. T23S R3W S7 DCS BT
16" D.Fir N.28°E., 23.3 ft. mkd. T23S R3W S6 DCS BT
No trees close to the N.W.
Corner on Douglas-Lane County Line.

Lane Co. Surveyor's Office - Crew: Bruce Bothel & Stuart Duce
- Nov. 30, 2016 (DCSO downloaded from LCSO website 4/13/2023
and added to DCSO records) - C.S. File 65/111-43

Found - At the corner position a 2½" DCSO brass cap
(properly mkd), atop a 1½" iron post, 7" above
grade.
1959 - A 25"x4' tall rotting fir stump with a healed
face bears S.9°50'W., 10.6' to ctr (N.9°E, 10.2'
To "W" nail).
1959 - A 25"x4' tall rotting fir stump with a healed
face bears N.28°E., 24.0' (S.28°W., 23.3' TO "W"
nail).
1959 - A 60"x3' tall rotting fir stump bears
S.84°19'E., 8.43' to "W" nail in face, 10.7' to
ctr (N.85°W., 8.8' to 'W' nail).
1959 - 54" broken top live Fir, no mks, N.69°W.,
2.84' to a set mag nail w/washer in face.

New - 5/8"x30" rebar with 2" alum cap "LCSO-RP1-2016" 4"
below ground N.26°49'00"E., 27.88'
5/8"x30" rebar with 2" alum cap "LCSO-RP2-2016" 4"
below ground S.66°21'E., 20.86'
9" Fir, mkd "CSBT" S.22°10'W., 24.4' to ctr.

Note - BTs, Distance shown is to an aluminum nail set at
side/center of live trees.
Basis of bearing: N.28°E., from section corner to
1965 (DCSO BT)

Geographic map location: For finding the corner area - not of
survey grade accuracy NAD 83/91 values:
Latitude: N 43°35'28.9" Longitude: W 123°06'26.3"
Equipment used: LEICA TCR 1203 & TRIMBLE TSC2 DATA COLLECTOR.

Brent Knapp - For: Weyerhaeuser Co. - 8/2023 - M182-54

Found - 1965 DCSO brass cap
Aluminum cap stamped "LCSO-RP1-2016"; N.26°49'E.,
27.88' continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12; 6 & 7, T23-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Aluminum cap stamped "LCS0-RP2-2016"; S.66°21'E., 20.86'
23" Fir stump, healed scar & tag N.28°E., 23.3'
(bearings reversed in LCS0 record)
40" Fir stump, healed scar & tag; S.85°E., 8.8'
(bearings reversed in LCS0 record)
25" Fir stump, healed scar & tag; S.9°W., 10.2'
(bearings reversed in LCS0 record)
10" Fir, healed scar & tag; S.22°10'W., 24.4'
54" broken top live Fir; N.69°W., 2.84' (to mag nail w/washer in face)
No evidence of original BTs found.