

PRIMARY CORNER DESCRIPTION SE Cor. R. Smith DLC #47

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1854</p> <p>-----</p> <p>Set stone post 10x10x15 inches for SE cor., from which A B.Oak 24" dia., bears N.70°W., 444 lks. A B.Oak 24" dia., bears N.28°E., 306 lks.</p>
<p>Douglas Co. Surveyor Office - N.E. Richardson, Milo Godfrey -Sept. 25, 1950 - C.S. File 44/63</p> <p>-----</p> <p>Found - Original stone for corner, 10" x 10" x 15", mkd. with "X" and "47". Blazed and scribed new BTs: 18" Pine N.7°W., 21.4 ft. 8" Fir, South 16.2 ft.</p>
<p>Fd. OK, March 1983, D. Bentz, M 93-76 A,B,C</p>
<p>Survey by Donald Bentz - For: Dan Webb - Dec. 1983 - M 95-78</p> <p>-----</p> <p>Found - "X" in stone and bearing trees: 24" Fir bears S.4½°W., 16.1 ft. No noticeable scar. 12" Fir bears N.66°E., 14.3 ft. Noticeable scar.</p>
<p>(Note: the 12" Fir does not seem to be of record. Bentz also found this tree on an April 1983 survey, M 93-76)</p>
<p>Fd. OK, August 1991, D.Bentz, M 113-71 and Fd. OK, Oct. 1993, M 118-8 Fd. OK, Aug. 1995 by D.Bentz - Rice Hill West, V. 19 P. 1</p>
<p>Do. Co. Surveyors Office - Larry E. Monrean & Randall Smith - Aug. 14, 1996 - C.S. 64/69-19</p> <p>-----</p> <p>Mon. Fd.- Stone top measures 10"x8" marked "47 +" on top protrudes 8" above ground. (orig. cor. stone) Bt's Fd.- Brg. & Dist. taken from "+" on top of corner stone. 8" now 24" dia. 4' high D.Fir stump with a fully healed blaze, bears South 16.2'. (Agrees w/1950 DCSO rec) 18" pine, bears N.7°W., 21.4' from 1950 not fnd. 12" now 16" dia. 2' high D.Fir stump, with a fully healed blaze, we opened and found illegible scribe marks, bears N.66°E., 14.9'. Source unknown approx 25 yrs. of growth on blaze. (Cont. next page)</p>

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 047060

PRIMARY CORNER DESCRIPTION SE Cor. R. Smith DLC #47

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

24" now 36" dia. B.Oak down and rotted no scribing or blazes found. Root Hole near orig. rec. (N.70°W., 293 ft.)
Orig. NE BT not found.

New Accessories -
3" dia. DCSO drill cap stamped "B02 SE DLC 47 1996" is set near middle at southerly edge of a 6' long by 4' wide ½' high rock out crop that has a N.75°E. orientation. Drill cap bears N.79°W., 62.9'.
3" D.Fir, double blazed and scribed "X BT", bears N.2°E., 11.3'.

New Accessories Cont.-
3" dia. DCSO Drill cap stamped "B01 SE DLC 47 1996" is set at easterly end of a 12' long by 6' wide 1' high rock out crop that has a N.30°W., orientation. Drill cap bears S.58°W., 45.3'.
8" maple double blazed and scribed "SE DLC 47 CS BT", bears S.7°W., 57.4'.

Location & Comments -
Metal witness post & sign is set 1' north of cor. Corner lies approx. 225' easterly of railroad tracks.

Fd. OK by K. DeGroot, Nov. 1998 - M130-78

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 11/28/2006 - C.S. File 67/14-47

FD. OK as per 1996 renewal.

FD. orig. stone, 7/2018 by D.Edwards, M174-55A

2