

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Robert Elder & Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO recs Vol. 6 Pg 2374)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Y.Oak 14" dia., bears N.72°W., 10 lks. A Y.Oak 16" dia., bears S.75°E., 38 lks.</p>
<p>Theil - For: Thompson & McKinney - 4/1902 - C.S. 64/48 Pg 17</p> <p>-----</p> <p>Set a Fir post, marked A Fir 12" S.3°W., 58 lks.</p> <p>-----</p> <p>(On survey for Caster and Benton, 1908, Theil states "Set Wh. Oak post") C.S. File 64/48 Page 17</p>
<p>Gilbert Gardner - For Yoncalla Lumber Co - April 1956 - M2-61</p> <p>-----</p> <p>Found - 2" I.P. in fence cor., from which 24" Fir stump S.3½°W., 38 ft. "BT" still visible. Reestablished BTs: 18" Fir S.19°E., 33 ft. 26" Oak N.22°E., 127 ft.</p>
<p>Survey by Wilford N. Haines - March 1967 - M 33-15</p> <p>-----</p> <p>Found - 2" cast Iron casing at fence corner. (See M 2-61) Stump hole of 16" Oak S.75°E., 38 lks. Stump of Fir BT S.3°43'W. 38.6 ft scribed 50-80 yrs 28" Fir S.18°36'E., 38.6 ft. Did not open. 28" Oak N.21°28'E., 126.0 ft. Did not open.</p>
<p>Fd. OK, July 1993, Ken Hoffine, M 117-52</p>
<p>DCSO-GIS Corner visitation - 5/2/2007 - Typed: 1/20/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - 2" pipe w/flange Comment - 1 live BT</p>
<p>Ron Rice - For: Fruit Growers Supply Co. & Guistina Tree Farm LP - July 2013 - M165-54</p> <p>-----</p> <p>Found - 2" pipe with flange 28" fir stump bears S.19°E., 33.6' - healed face 35" Oak bears N.22°E., (rec. S.22°W., M117-52) 126.6' - healed face.</p> <p>New - 13" D.Fir bears N.89°W. 6.8' blazed-scribed ¼ S30 BT Corner lies 1' South & 2' east of fence corner. Steel post adjacent to corner.</p>