

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 140540

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Daniel Baker, L.S. #1978 - For: Weyerhaeuser Co. -  
Dec. 28, 1993 - M 118-43

-----  
Set 2" x 42" Iron pipe with brass cap, from which  
9" Madrone N.28°E., 53.0 ft.  
28" Cedar S.13°E., 27.2 ft.  
19" Fir S.34°W., 35.6 ft.  
20" Fir N.29°W., 37.5 ft.

Affidavit of Correction filed by D.Baker for survey map M  
118-43. Recorded Aug. 19, 1997 in Book 1488 Page 817, Co.  
Clerks records. See recorded document in C.S. File 65/14-  
9.

-----  
(Wording from Affidavit)

The center ¼ corner monument was found to have been set  
from the wrong transit hub. The corrected corner position  
was monumented on August 7, 1997 by this Company. The  
erroneous corner monument was removed and associated  
bearing trees chopped out. The brass cap as noted on the  
plat remains the same. All shown plat calls to the  
monument are correct and remain the same. Monument size  
and bearing trees have changed. The correct corner and  
information is as follows:

Set - 1½" x 36" iron pipe with 2½" brass cap dated 1997.  
9" Fir, N.73°E., 9.9 ft. to "W" nail.  
10" Fir, S.61°E., 17.1 ft. to "W" nail.  
9" Fir, S.31°E., 18.9 ft. to "W" nail.  
9" Fir, S.21°W., 2.4 ft. to "W" nail.

All bearings to bearing trees are magnetic 20°  
declination and scribed "C ¼ S7"

Fd. & used on BLM dependent resurvey by Wayne Rogers &  
Bryan Seibold, Cadastral Surveyors, under Group #1832  
surveyed July-Oct. 1997 - (DCSO recs. Vol. 53 Pg(s) 20286)