

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2376)

Set ¼ sec. post, from which
A Fir 18" dia., bears N.49°E., 42 lks.
A Fir 16" dia., bears N.33°W., 41 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Nov. 1959 - C.S. File 49/42-22

Found - Orig. 18" now 38" Fir, stump, N.49°E., 27.7 ft. I open near base and find good scribing "BT"
Orig. 16" now 30" Fir N.33°W., 27.1 ft., shows good scribing on old face "BT". This BT has been bark scribed "¼S"

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 5 W
¼ S19|S20
1959

New BT - 12" R.Fir bears S.34°E., 35.8 ft. scribed ¼ S20 CSBT
Cor. lies easterly 12" from fence row, fence running N-S

Fd. OK, Dec. 1989, C.S. File 63/104-48
Fd. Ok by Ken Hoffine, 1/2006 - M149-61

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2315, Surveyed May/June 2010 - DCSO records Vol. 57 Page(s) 22770-1

The ¼ sec. cor. of secs. 19 & 20, perpetuated by Byron, in 1959, monumented with an iron post, 1¼" dia., firmly set, projecting 15" above the ground with brass cap (properly) mkd from which the remains of the original bearing trees

A sawed, decayed fir stump, 36" dia., bears N.49°E., 27.7 ft., with an axe mark visible on the bark.

A roothole bears N.33°W., 27.1 ft alongside of which is a decayed fir trunk, size indeterminate, with no marks visible.

and remains of a bearing tree mkd. by Byron

A sawed fir snag, 23" dia bears S.35½° 35.9 ft., with a healed double blaze

and new bearing trees

A fir, 4" dia bears S.50°E., 23.6 ft.. mkd. X BT.

A fir, 10" dia., bears S.35°W., 7.7 ft., mkd. ¼ S19 BT