

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2369)

Set ¼ sec. post, from which
A Fir 16" dia., bears N.19°E., 62 lks.
A Fir 9" dia., bears N.61°W., 83 lks.

Survey by Glenn Baughman - July 1971 - RM 2-29

Set by proportionate measurement
Found - 6" D.Fir N.77°E., 12.4 ft.
Set - 1" x 30" I.Pipe with brass cap.
Marked - 8" D.Fir S.73°W., 18.3 ft.

BLM dependent resurvey by Wayne Rogers & Bryan Seibold, Cadastral Surveyors, under Group #1832 surveyed July - Oct. 1997 - (DCSO recs. Vol. 53 Pg(s) 20276)

The ¼ sec. cor. of secs. 20 & 21, reestablished by proportionate measurement by Baughman, in 1971, there is no remaining evidence of the original corner, therefore, this position is accepted as the corner; monumented with an iron post, 1½" diam., firmly set, projecting 14" above ground, with brass cap mkd.

T 23 S R 5 W
1/4 20|21
1971
OLS 536

from which a bearing tree mkd. by Baughman
A fir, 15" diam., bears N.71 ¾°W., 28½ lks., with healed double blaze.

and the remains of a bearing tree mkd. by person(s) unknown and recorded by Baughman

A sawed fir stump, 12" diam., bears N.80½°E., 18½ lks., with healed blaze.

and a new bearing tree

A fir, 14" diam., bears S.1½°E., 78 lks., mkd. ¼ S21 BT.
The corner is located on the west edge of a clear-cut.

Douglas Co. Surveyors Office - Stephen J. Flauser - John Pike - 11/28/2006 - C.S. File 67/14-47

Both 1997 renewal trees are now high stumps. Corner falls in recent clearcut area. No suitable trees within a reasonable dist.