

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. cor. for 4 & 5 only, N. bdy.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2337)

Set post, cor. to secs. 4 and 5, from which
A Fir 18" dia., bears S.58°E., 50 lks.
A Maple 9' dia., bears S.45°W., 3 lks.

Survey by Wilford N. Haines - For: S. Mathis - Oct. 21, 1959
M 16-3

Found - 36" Fir stump of BT, S.58°E., 50 lks.
Drove 1" x 1" x 12" T. Iron into ground next to bank of a road.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Dec. 1959 - C.S. File 49/42-36

Found - Orig. 18" now 38" Fir stump, previously opened, shows good scribing "5"
SW BT gone.
Angle iron set by Haines.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S

S 5 | S 4 R5W

T 23 S
1959

New BTs -12" R.Fir bears S.45°E., 89.4 ft. scribed S4 T23S R5W CS BT.
8" R.Fir bears S.19°W., 14.0 ft. scribed S5 T23S R5W CS BT.

Corner is at West edge of old log road.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - J.H. Cook, crew - Feb. 18, 1976 - C.S. File 59/8-1

Found - 1959 DCSO brass cap, out of ground, on edge of road properly stamped.
Orig. 18" now 38" Fir stump bears S.58°E., 33.0 ft. scribed "R5W T23S 4"
12" now 16" R.Fir bears S.45°E., 68.4 ft. (Rec. 89.4 ft.) Tree has good blaze, tagged.
8" now 11" R.Fir bears S.16½°W., 14.0 ft. (Rec. S.19°W.) Tree has good blaze, tagged.

Reset Brass cap at section corner, cap stamped as noted. Corner lies on edge of road. Set fence post and sign beside monument.

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec cor for 4 & 5 only, N. bdy

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed 1982 (DCSO records Vol. 46 Page(s) 17668)

The standard cor. of secs. 4 & 5, perpetuated and recorded by Byron in 1959, determined at record bearing and distance from the remains of an original bearing tree

A sawed Fir stump 36" dia., bears S.58°E., 50 lks. dist., with fragmentary scribe marks visible on opened blaze. and bearing trees mkd. by Byron

A Fir 19" dia. bears S.46¼°E., 104 lks. with healed blaze.

A Fir 15" dia., bears S.16°W., 23 lks., with healed blaze.

At the corner point

Set an alum. post, 28" long, 2 1/2" dia., 33" in the ground, the top 5" below the surface of road, with alum. cap mkd:

S 5 | S 4
T 23 S | R 5 W
SC
1982

The corner is located in dirt road, 15 lks. wide, bears N.25°W. and S.25°E.

Fd. OK, Feb. 1994, K. Hoffine, M 118-66

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 1/4/2006 - C.S. File 67/14-1

Found - 3" dia., alum (properly) marked, 5" below surface on West side of logging road.

36" Fir stump now indeterminate dia., 3 ft. tall rotting stump previously opened face with faint marking visible bears S.58°E., 33.0 ft. (agrees w/rec) Orig. BT

16" R.Fir now 18" dia., x 3½ ft. tall stump fully healed blaze visible, bears S.46½°E., 68.4 ft. (rec. S.45°E., 89.4 ft.) 1959 BT

11" R.Fir now 15" dia., x 1½" tall stump fully healed blaze visible, bears S.16½°W., 14.0 ft. (rec. S.19°W., 14.0 ft.) 1959 BT

New - 11" dia., D.Fir double blazed & scribed "SC CS BT" bears N.1°W., 29.5 ft.

15" dia., D.Fir double blazed & scribed "T23S R5W SC S4 CS BT" bears S.41°E., 42.7 ft.

Note - Lies on westerly side of old logging road, approx. 3 ft. from edge.

Fd. Ok by D. Edwards - 7/2013 - M165-45 A&B