

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2364)

Set post, cor. to secs. 9, 10, 15 and 16, from which

- A Y.Oak 14" dia., bears S.46°E., 126 lks.
- A Y.Oak 15" dia., bears S.20°W., 89 lks.
- A Y.Oak 16" dia., bears N.48½°W., 80 lks.
- A Y.Oak 16" dia., bears N.75°E., 109 lks.

Survey by Gene E. Johnson - Jan. 1957 - C.S. File 42/218 and M 5-40

Found - Orig. BT and chopped out scribe, a 24" Oak S.46°E., 71.60 ft.

Two other Oaks appear to fit for old BTs but show no sign of scars:

- 30" Oak N.48½°W., 81.2 ft. (O.B.T.)
- 30" Oak N.75°E., 70.8 ft. (O.B.T.)

At corner point, set 3/4" x 30" iron rod, from which

- 12" Fir bears N.53°30'W., 15.3 ft. scribed T23S R5W S9 R.E. 3561 BT.
- 18" B.Oak bears N.37°45'E., 11.7 ft. scribed T23S R5W S10 R.E. 3561 BT.
- 7" Fir bears S.60°30'E., 19.6 ft. scribed T23S R5W S15 R.E. 3561 BT.
- 5" W.Oak bears S.9°30'W., 31.2 ft. scribed T23S R5W S16 R.E. 3561 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Jan. 19, 1960 - C.S. 49/42-49

Found - One orig. BT only, orig. 14" now 33" B.Oak S.46°E., 83.2 ft., shows parts of good reverse scribing. Johnson renewed this corner. He found same orig. BT, used record bearing but used 71.6 ft. (Rec. 83.2 ft.) I leave 3/4" I.R.s et by Johnson for corner which is under new fence. I destroy scribing on his SW BT.

Also found stump holes that check record for NW and NE BTs.

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S R 5 W
 S 9 | S10
 S16 | S15
 1960

(Cont. Next Page)

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

New BTs -15" R.Fir S.18°W., 27.2' scribed S16 T23S R5W CS BT.
7" R.Fir S.49°E., 47.9' scribed S15 T23S R5W CS BT.
24" B.Oak N.83°E., 15.5 ft. (Johnson's BT)
15" R.Fir N.65°W., 4.4 ft. (Johnson's BT)
Johnson's BTs not rescribed.

Douglas Co. Surveyors Office - Randall Smith, party chief,
Terrie Frannsen, crew - March 20, 1987 - C.S. File 62/40-3

Found - 1960 DCS0 brass cap on a 1½" O.D. I.P., protruding
9" above ground.
A ¾" Iron rod protruding 8" above ground, top bent
4" North, bears S.50 ¾°E., 10.9 ft.
(All bearings and distances to 1960 County Brass cap)
14" now down and rotted, indeterminable size Oak, no
scars, blazes or scribing found, bears S.46°E.,
83.2 ft. (agrees well with record) Orig. BT.
16" now possible stump hole found, no other evidence
found, bears N.75°E., 71.94 ft. (agrees well with
record) Orig. BT.
24" now 29" B.Oak with a fully healed double blaze
bears N.83°E., 15.5 ft. (Brg. & Dist. per 1960,
scribed in 1957)
15" now 17" D.Fir with a fully healed double blaze
bears N.65°W., 4.4 ft. (Brg. & Dist. per 1960,
scribed in 1957)
15" now 24" D.Fir with a fully healed double blaze
bears S.18°W., 27.2 ft.
7" now 16" D.Fir with a fully healed double blaze
bears S.49°E., 47.9 ft.
¾" Iron rod protrudes 8" above ground, top bent 4"
North, (brg. & dist. taken to plumb position)
bears S.50 ¾°E., 10.9 ft. designated as corner
per Johnson (Rec. S.46°E., 11.6 ft. computed from
Johnson's tie to orig. SE BT and Byron's tie to
orig. SE BT.)

New Accessories:

5/8" x 30" I.Rod with DCS0 alum. cap stamped "B01
1987" set flush with ground brs N.34°E., 14.5 ft.
5/8" x 30" I.R. with DCS0 alum. cap stamped "B0 2
1987" set flush with ground brs S.47½°W., 64.5 ft.
5/8" x 30" I.R. with DCS0 alum. cap stamped "B0-
1987" set flush with ground brs N.37°W., 54.2 ft.

Cor. lies approx. 150' NE of house & 9' East of gravel drive-
way. BC/IP to be destroyed in near future, a garage is to be
located at cor. position.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause,
Deputies - May 4, 1988 - C.S. File 62/52-15

(Area around corner's position has been recently excavated.
A garage is to be located at the corner position in near
future.)

Found - DCS0 2½" dia. Brass cap on a 1½" I.P. was found out
of ground in N-S fence line near corner.

3/4" Iron rod protruding 8" above ground, top bent
4" North.

5/8" Iron rod protruding 1" above ground, recently
set, bears West, 0.5 ft. of a point calculated
from BTs and B0's (Calc. point not set) (I.R. set
by H. Northcraft)

(Bearings and distances taken to a calculated point):

14" now down and rotted, indeterminable size Oak, no
scars, blazes or scribing found, bears S.46°E.,
83.2 ft. Orig. BT.

16" now possible stump hole, bears N.75°E., 71.9 ft.
Orig. BT.

24" now 29" dia. B.Oak with a fully healed double
blaze bears N.83°E., 15.5 ft.

D.Fir bearing N.65°W., 4.4 ft. now gone.

15" now 24" dia. D.Fir with a fully healed double
blaze bears S.18°W., 27.2 ft.

7" now 16" dia. D.Fir with a fully healed double
blaze bears S.49°E., 47.9 ft.

3/4" Iron rod protrudes 6" above ground, top bent 4"
North (Brg. & Dist. taken to plumb position)
bears S.50 3/4°E., 10.9 ft.

5/8" I.R. with a DCS0 alum. cap stamped "B01 1987"
flush with ground, bears N.34°E., 14.5 ft.

5/8" I.R. with a DCS0 alum. cap stamped "B02 1987"
flush with ground, bears S.47½°W., 60.5 ft. (Rec.
S.47½°W., 64.5 ft., dist. was in error)

5/8" I.R. with alum. cap bearing N.37°W., 54.2 ft.
not found. Approx. 2½ ft. of new dirt and gravel
at this position.

No new monument or accessories set.

Corner lies approx. 150 ft. NE of house and 8½ ft. West of a
N-S fence line. In near future, a garage is to be located at
corner position.

Douglas Co. Surveyors Office - Randall Smith and Stephen
Flause, crew - April 11, 1989 - C.S. File 62/63-6

CORNER REPORT ONLY
(Cont. Next Page)

