

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec Cor for 13, 14, 23 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2350)

Set post, cor. to secs. 13, 14, 23 and 24, from which
A Y.Oak 15" dia., bears S.17 3/4°E., 102 lks.
A Fir 14" dia., bears S.51°W., 65 lks.
A Fir 28" dia., bears N.81°W., 44 lks.
A Y.Oak 30" dia., bears N.4°E., 577 lks.

Survey by Gene E. Johnson - For: E.A. Hostetler - Oct. 1954
C.S. File 41/318 and M 12-48

Found - 14" Fir, now 66" S.51°W., 65 lks. O.B.T.
Down BT, 28" Fir, now 60", N.81°W., 44 lks.
Set 2" galv. Iron pipe at corner point.
Blazed and scribed 4 BTs:
24" Fir N.4°W., 65.8 ft.
18" Fir N.14°45'E., 67.2 ft.
15" W.Oak S.72°30'E., 21.1 ft.
20" B.Oak S.32°30'W., 48.5 ft.

Douglas County Surveyors Office - Vernon "Ray" Tracy, Jack Heritage and V. Perron - Oct. 1969 - C.S. File 54/16-61

Found - No trace of 2" corner pipe by Johnson.
15" now 16" W.Oak, alive, S.72½°W., 21.1 ft., healed blaze.
20" now 21" B.Oak, alive, S.32½°W., 48.5 ft. healed blaze.
NE and NW Fir BTs, now stumps, scribe marks visible.
Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 5 W
S 14 | S 13
S 23 | S 24
1969
Cap 8" below surface.
New BTs -16" B.Oak N.1°W., 82.0 ft. mkd. T23S R5W S14 CSBT
24" W.Fir N.66°E., 13.5 ft. mkd. T23S R5W S13 CSBT
Orig. BT to SW., now low cut stump.
This corner lies in logging road, course N.

Found and used, BLM dependent resurvey by Dale T. Bedell, Cadastral Surveyor, under special instructions dated April 30, 1991 under Group No. 1601, surveyed June 1991/July 1992

continued next page

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec Cor for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Mark Smalley - For: Roseburg Resources - Oct./Nov. 2002 - M137-55</p> <p>-----</p> <p>Found - 1969 Douglas County Surveyors iron pipe & brass cap. BTs - 44" W.Fir N.66°E., 13.5' healed 19" W.Fir S.72½°E., 21.1' healed (rec S.72½°W) 31" B.Oak S.32½°W., 48.5' healed B.Oak N.1°W., 82.0' down & decayed Scribed- 18" Fir S.41°W., 33.9' "S23 BT. Corner falls in old road, 11" below surface.</p>
<p>FD. ok by D. Edwards 9/2005 - M148-40</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 5/14/2007 - C.S. File 67/21-37</p> <p>-----</p> <p>Fd. ok, BC is in the middle of overgrown road 14" below surface.</p>
<p>Fd. as per record 4/2024 - D. Edwards - M183-55</p>