

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 636700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 36 only, T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1386)

Set ¼ sec. post, from which
A B.Oak 24" dia., bears N.60°W., 4 lks. dist.
A B.Oak 12" dia., bears N.80°E., 51 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Jan. 15, 1960 - C.S. 49/42-42

Found - Orig. 12" B.Oak, now down, N.30°E., 33.7 ft. I open and find good scribing "B"
Orig. 24" now 40" B.Oak N.60°W., 2.6 ft. shows good scars. I do not open.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 5 W
South ¼ corner S36
1960

New BTs -17" R.Fir bears N.10°E., 17.5 ft. scribed S¼ S36 CS BT.
13" R.Fir bears N.33°W., 26.1 ft. scribed S¼ S36 CS BT.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause, Crew - Feb. 24, 1986 - C.S. File 62/31-1

Found - 1960 DCSO Brass cap/I.P., bent and leaning 0.8 ft. northwest of plumb position, protrudes 7" above ground.

Orig. BT, 24" now 40" B.Oak shows a single well healed face, bears N.60°W., 4.0 ft. (Rec. N.60°W., 2.6 ft. to face.)

17" now 22" D.Fir with a fully healed double blaze bears N.10°E., 17.5 ft.

13" now 21" D.Fir with a fully healed double blaze bears N.31°W., 26.1 ft. (Rec. N.33°W., 26.1 ft. is to center of trunk at level distance.)

Iron pipe straightened and returned to plumb position. I.P/BC protrudes 3" above ground.

New BT - 8" dia. D.Fir double blazed, scribed "¼S36 CS BT" bears N.82½°E., 24.0 ft.

Fd. OK, Oct 1992, K.Hoffine, M 116-2