

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE Tsp. Cor. (NE Cor. Sec. 1)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - James E. Freeman Deputy Surveyor, under Contract #1, dated May 28, 1851 (DCSO recs Vol 6 Pg 2268-69)

Set post cor. of Tps. 22 & 23 S. bet. Ranges 4 & 5 W., from which

An Alder 12" dia., bears S.13 3/4°E., 745 lks. dist.

An Alder 9" dia., bears S.16 1/2°W., 725 lks. dist.

A W.Oak 14" dia., bears N.80°W., 1653 lks. dist.

Made trench as per instructions.

Douglas Co. Surveyors Office - James W. Byron; M. Godfrey; S. Bilow, crew - Dec. 4, 1957 - C.S. File 49/42-46

Found - Orig. 14" now 33" W.Oak N.80°W., 1091.0 ft. This bearing tree opened and rescribed about 20 years ago, probably by Theil. I open inside shell and find good scribing (negative). I reblaze and rescribe this BT, "T22S R5W S36 CS BT".

Other BTs for this corner gone.

I also find 1 1/2" I.P. 4.4 ft. North of temp. corner.

Sketch in file. This corner not renewed because the distance to BT is too great to fix corner location.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Jan. 25, 1960 - C.S. 49/42-46

(Standard cor. for Secs. 1 & 6, Tsp. 23 Ranges 4 & 5)

Found - Orig. 14" now 34" W.Oak N.80°W., 1091.0 ft. Theil rescribed this BT years ago. I open back of his scribing and find orig. scribing "WR"

Also find 2" Iron pipe at corner. Turpin says Theil set this pipe for corner.

Closing corner 4.59 chs. West, not found.

New BT - 26" Maple bears N.80 1/2°W., 475.0 ft. scribed S36 T22S R5W CS BT.

No other trees near.

3/4" Iron rod with 4" x 4" white post bears S.55°E., 88.2 ft., mkd. SHRW L PT 722+72.44.

Fd. OK, Dec. 1964 by DCSO - C.S. File 53/101-52

Fd. OK, Oct. 1979 - C.S. File 62/63-20

Fd. Ok by N. Hibbs Oct. 2004 M145-59

DCSO-GIS Corner visitation - 5/18/2004 - Typed: 1/20/2011 - C.S. File 67/33-1

Monument - 2"

Comment - (Needs) rehab