

PRIMARY CORNER DESCRIPTION SW Tsp. cor. (SW Cor. Sec. 31)

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2390)

 Set post cor. to Tps. 23 and 24 South, bet. Rs. 6 & 7, from which

- A Fir 15" dia., bears N.57°E., 18 lks.
- A Fir 18" dia., bears N.12°W., 28 lks.
- A Laurel 12" dia., bears S.82°W., 20 lks.
- A Fir 12" dia., bears S.84°E., 70 lks.

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2517)

 Set a Fir post for the cor. of secs. 31 and 36. Tps. 23S., R 6 & 7 W., from which

- A Fir 18" dia., bears N.8°E., 50 lks. dist.
- A Fir 16" dia., bears N.24°W., 60 lks. dist.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12649)

 Point for the cor. of Tps. 23 and 24 S., Rs. 6 & 7 W., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd.

T23S	
R7W	R6W
<u>S36</u>	<u>S31</u>
S 1	S 6
T24S	
1957	

from which

- A Fir 22" dia., bears N.75½°E., 117 lks. dist., mkd. T23S R6W S31 BT.
- A Fir 20" dia., bears S.63°E., 193 lks. dist., mkd. T24S R6W S6 BT.
- A Fir 12" dia., bears S.82°45'W., 143 lks. dist., mkd. T24S R7W S1 BT.
- A Fir 18" dia., bears N.66°45'W., 184 lks. dist., mkd. T23S R7W S36 BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION SW Tsp. cor. (SW Cor. Sec. 31)

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Contract #244, surveyed April/May 1964 (DCSO records Vol. 32 Page(s) 13497)

Point for the cor. of Tps. 23 and 24 S., Rs. 6 and 7 W., at proportionate distance; there is no remaining evidence of the original corner.

From this point, the cor. of Tps. 23 and 24 S., Rs. 6 and 7 W., erroneously reestablished by Eggen, in 1957, bears South, 0.275 chains dist., set, marked and witnessed as described in the official record. I remove the iron post, destroy the marks on the NE. and SE. bearing trees, and at the corner point

Reset the iron post, 36" long, 2" dia., 20" in the ground, with brass cap mkd:

	T 23	S
R 7 W		R 6 W
	S 36	S 31
	S 1	S 6
R 7 W		R 6 W
	T 24	S
	1957	

from which new bearing trees

A Fir 8" dia., bears N.63°E., 111 lks. dist., mkd. T23S R6W S31 BT.

A Cedar 15" dia., bears S.85°E., 163 lks. dist., mkd. T24S R6W S6 BT.

and bearing trees mkd. by Eggen in 1957

A Fir 13" dia., bears S.73°W., 151 lks. dist., with a healed blaze.

A Fir 22" dia., bears N.74½°W., 177 lks. dist., with a healed blaze.

Cor. referenced out May 23,1972 for road work, DCSO, C.S. File 59/30

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - R.B. Kimberling, M.W. Cline, crew - Aug.29, 1977 - C.S. File 59/38-21

Found - All evidence of the orig. corner is gone.
Found a BLM brass cap reset by unknown party approx. 0.5 ft. from proper location. This corner was referenced by DCSO in 1972 for road construction per notes attached to field notes for this renewal visit.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION SW Tsp. Cor. (SW cor. Sec. 31)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found a 5/8" I.Rod and PK nail in stump established as references for this corner, N.84½°E.
 The SE references have been destroyed.
 WE RESET the BLM brass cap at the proper location as determined by transit and chain from the DCSO references.
 Found - A 22" now 23" G.Fir with well healed blaze bears N.74½°W., 115.6 ft. (Rec. N.74½°W., 116.8 ft.) 1957 BLM BT.
 The NE BT has been destroyed. (1957)
 From the 1964 BLM resurvey correcting the 1957 resurvey: An 8" now 12" D.Fir alive, with well healed single blaze bears N.63°E., 73.3 ft. and a 15" now 17" I.Cedar with scribing "S R6W S6" visible on partially healed single blaze bears S.85°E., 107.6 ft.
 RESET the BLM iron post with brass cap attached mkd. as described in the official record, flush in the shoulder of a dirt logging road. We add the markings "RESET 1977" to the brass cap.
 No new accessories. We place a steel fence post with survey marker witness sign attached approx. one foot west of brass cap.

Douglas Co. Surveyors Office - Randall Smith, Deputy - Stephen Flause, crew - Jeb. 7, 1992, C.S. File 64/2310

 Found - 3½" dia. BLM brass cap on iron pipe is flush with ground. (1957 BLM - reset 1977)
 22" now 35" dia. G.Fir with a fully healed single blaze, bears N.74½°W., 115.6 ft.
 8" now 15" dia., D.Fir with a fully healed single blaze, bears N.63°E., 73.3 ft.
 15" now 22" dia. I.Cedar with a fully healed single blaze, bears S.85°E., 107.6 ft.
 New BT - 8" dia. D.Fir double blazed and scribed "T24S R7W S1 CS BT" bears S.45°W., 19.3 ft.

*NOTE: BLM survey suspended Sept. 1983; lifted Feb. 1985; and suspended again Feb. 6, 1992. **Suspension lifted, June 21, 1996, file 9632 (OR942)***

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/August 22, 1995 - (DCSO records Vol. 51 Page(s) 19452-53)
 ----- (Cont. Next Page)

PRIMARY CORNER DESCRIPTION SW Tsp. corner (SW Cor. Sec. 31)

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Point for the cor. of Tps. 23 and 24 S., Rs. 6 and 7 W., at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T23S
 R7W R6W
 S36 | S31
 S1 | S6
 R7W R6W
 T24S
 1993

from which

A fir, 9 ins. diam., bears N. 33° E., 18½ lks. dist., mkd. T23S R6W S31 BT.

A fir, 7 ins. diam., bears S. 35° E., 32 lks. dist., mkd. T24S R6W S6 BT.

A fir, 7 ins. diam., bears S. 28° W., 16 lks. dist., mkd. T24S R7W S1 BT.

A fir, 7 ins. diam., bears N. 67° W., 16½ lks. dist., mkd. T23S R7W S36 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the cor. of Tps. 23 and 24 S., Rs. 6 and 7 W., at latitude 43° 31' 09.776" N. and longitude 123° 27' 52.045" W. (NAD 1927), determined by Douglas County Surveyor's Office in 1992, erroneously reestablished by Brooks in 1964, bears S. 56° 53' 00" E., 1.130 chs. dist., monumented with an iron post, 2½ ins. diam., firmly set, projecting 2 ins. above ground, with brass cap mkd. T23S R7W R6W S36 S31 S1 S6 R7W R6W T24S 1957 RESET 1977. This monument had been referenced and removed for road construction and then reset at the same position by the Douglas County Surveyor's Office in 1977 from which a bearing tree mkd. by Gould, Gawron, and Eggen:

A fir, 30 ins. diam., bears N. 74¼° W., 176 lks. dist., with healed blaze.

and bearing trees mkd. by Brooks

A fir, 14 ins. diam., bears N. 62° E., 112 lks. dist., with healed blaze.

A cedar, 22 ins. diam., bears S. 86° E., 163 lks. dist., with healed blaze.

and a bearing tree mkd. by Smith & Flause, Douglas County Surveyor's Office, in 1992

A fir, 7 ins. diam., bears S. 43¼° W., 29 lks. dist., with scribe marks T24S R7W S1 CS BT visible on an open blaze.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. Cor)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Amended the brass cap to read T23S R7W R6W S36 S31 S1 S6 R7W R6W T24S 1957 RESET 1977 AMENDED 1993, reset the monument flush with the ground surface, and obliterated the marks on the bearing trees.

Fd. and used in BLM resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1637, surveyed May 1992/April 1993 - (DCSO records Vol. 51 Page(s) 19541)

Fd as per rec. D.Edwards, 2/2019 - M175-23