

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 5 & 6 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1429)

-----  
Set standard cor. to secs. 5 and 6, from which  
A Fir 48" dia., bears S.25°E., 8 lks. dist.  
A Fir 24" dia., bears S.32°W., 27 lks. dist.

GL0 survey by Carl S. Nicklin, Deputy Surveyor, under Special Instructions dated Oct. 27, 1897 (DCSO records Vol. 4 Page(s) 1466)

-----  
I reestablish at same point from the bearing trees, which I find standing as follows:  
Set a Fir post, 3 ft. long, 4" sq., 24" in the ground, for a standard cor. of secs. 5 and 6, mkd. S C T23S R6W on S.; S5 on E.; and S6 on W. faces; with 5 grooves on E. and 1 groove on W. faces; from which  
A Fir 28" dia., bears S.25°E., 8 lks. dist. mkd. T23S R6W S5 BT.  
A Fir 30" dia., bears S.32°W., 25 lks. dist., mkd. T23S R6W S6 BT.  
This standard cor. is on the NE. slope of spur.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - N.E. Richardson; Fred Southwick, wit. - Sept. 18-19, 1930 - C.S. File 37/31 (and "old" corner book, page 37)

-----  
Location identified from orig. BTs as follows:  
Snag of OBT, S.32°W., 27 lks.  
54" Fir S.25°E., 8 lks.  
Drove a tack in root for corner with Cedar post, 4x6x36 ins. alongside.  
Reblazed and scribed orig. BT, 54" Fir S.25°E., 8 lks. "SC T23S R6W S5 CS BT."  
Blazed and scribed 12" double Hemlock S.86°W., 119 lks. "SC T23S R6W S6 CS BT"

Wilford N. Haines #239 - For: Irvin Rice and Whipple Mill - 1954/1955 - C.S. File 42/13 (M 112-74)

-----  
Found tack in root and one BT.  
At corner point, set an angle iron with brass cap inscribed "Survey point, Wilford N. Haines #239"

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12631)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 5 & 6 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

The standard cor., monumented with a Cedar post, 4 ft. long, 2x6 ins. in cross section, mkd. T23S R6W S5 SC on E. face and T23S R6W S6 SC on W. face; and alum. cap, 1" dia., mkd. Wilford N. Haines, 239, Drain, Oregon, Survey Point, from which the remains of the original bearing trees:

A Fir 54" dia., bears S.25°E., 8 lks. dist., with a chopped blaze.

A stump bears S.32°W., 25 lks. dist.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 30" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

T22SR6W  
S 32  
S 6 | S 5  
T23SR6W  
S C  
1955

from which

A Hemlock 16" dia., bears S.29°E., 47 lks. dist., mkd. T23S R6W S5 SC BT.

A Hemlock 10" dia., bears S.31°W., 79 lks. dist., mkd. T23S R6W S6 SC BT.

Reset Cedar post alongside the iron post, reset alum. cap alongside the Cedar post.

Wilford N. Haines, June 29, 1962 - C.S. File 51/222-3  
-----

Found - Brass cap set by GLO, pulled out, set back in same hole.

Orig. Fir BT, now 60 ft. stump bears S.25°E., 5.3 ft. to face.

New BTs by GLO:

16" Hemlock S.29°E., 53.3 ft. (not 47 lks.)

10" Hemlock S.31°W., 47 lks. (not 79 lks.) (This tree is down)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Dec. 23, 1969 - C.S. 49/143-100  
-----

Found - 1955 Cadastral brass cap, nearly out of ground, properly mkd.

Orig. 54" Fir S.25°E., 5.3 ft. now stump, blaze burned.

1955 16" now 17" Hemlock S.29°E., 52.1 ft., now broken off 8 ft. above ground, record dist., 31.0 ft.

No trace of other BTs.

We reset brass cap.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 5 & 6 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BT - 16" hemlock N.28°E., 18.0 ft. mkd. "SC CS BT"  
No trees South of corner. This cor. lies on steep northerly slope about 100 ft. South of Squaw Creek course West.

Fd. OK, Oct. 1990, C.S. File 63/127

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2874, surveyed AUG. 2017- (DCS0 records Vol. 59 Page 23795 & Plat T23-6 2020-1)

-----  
The standard cor. of secs. 5 and 6 only, on the N bdy of the Tp. perpetuated by Douglas County Surveyor's Office, in 1969; monumented with an iron post, . 2½" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree

A sawed fir stump, 58" dia., bears S.25°E., 5.3 ft. with no marks visible on open blaze.

and a BT mkd by Douglas County Surveyors office in 1969

A hemlock, 24" dia., bears N.27½°E., 17.7 ft., with a healed double blaze.

and a new bearing tree

A fir, 11" dia., bears S.50½°E, 282 ft. mkd. 123S R6W S5 SC BT.

NAD 1983 (2011)

Lat: 43°36'22.65"N

Long: 123°26'43.50"W