

PRIMARY CORNER DESCRIPTION 1/4 sec. cor. for 20 and 29

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2444)

-----  
Set Fir post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which  
A Fir 5" dia., bears N.19°E., 28 lks. dist. mkd. 1/4 S BT.  
A Fir 6" dia., bears S.72°E., 15 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12705-06)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30" long, 2" dia., 22" in the ground, with brass cap mkd:

T23SR6W  
1/4 S 20  
S 29  
1957

from which

A Fir 20" dia., bears N.21°E., 73 lks. dist. mkd. 1/4 S20 BT  
A Fir 33" dia., bears S.49°W., 74 lks. dist. mkd. 1/4 S29 BT

Cor. Fd. and used in BLM resurvey by Jelley, Rogers, and Bishop, Contract #1098, surveyed June 1982/Nov. 1983 (DCSO records, Vol. 46 Page 17727)

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19504)

-----  
Point for the 1/4 sec. cor. at proportionate distance. There is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T23S R6W  
S20  
1/4 -----  
S29  
1994

from which a bearing tree mkd. by Gould, Gawron, and Eggen  
A fir, 26 ins. diam., bears N. 7° E., 95 lks. dist., with healed blaze.

and a new bearing tree

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 15 ins. diam., bears S. 42° E., 180 lks. dist.,  
mkd. ¼ S29 BT.  
Deposit a white "DEEP-1" magnetic marker at the base of the  
stainless steel post.

From this point, the ¼ sec. cor. of secs. 20 and 29,  
erroneously reestablished by Gould, Gawron, and Eggen in  
1943-57, bears N. 28° 06' 30" W., 0.299 chs. dist.;  
monumented with an iron post, 2½ ins. diam., firmly set,  
projecting 6 ins. above the ground, with brass cap marked and  
witnessed as described in the official record except the SW.  
bearing tree is a stump. Amended the marks on the brass cap  
to read AM 1994 1957, reset the monument inverted, and  
obliterated the marks on the stump.

Mark Smalley - Bill Olson - Ralph McManis - 3/8/2006 - C.S.  
File 65/58-5

-----  
Found - 1994 BLM stainless steel pipe & brass cap (properly  
marked).  
27" Fir, N.7°E., 62.7 good condition - healed face.  
19" Hemlock S.42°E., 118.8 good condition - healed  
face.  
New - 11" W.Fir N.32°E., 18.6' scribed "¼ S BT"  
10" D.Fir S.76°E., 22.7' scribed "¼ S BT"  
Note - Did not find inverted 1983 corner monument.  
Compass decl. 16°