

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2429)

Set Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 30" dia., bears S.20°E., 15 lks. dist. mkd. ¼ S BT.
A Fir 20" dia., bears S.39°W., 17 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12690)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 3 ft. long, 1" dia., 24" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:
T23SR6W
¼
S32|S33
1957

from which
A Fir 8" dia., bears S.9°45'E., 29 lks. dist. mkd. ¼ S33 BT.
A Fir 15" dia., bears N.83°30'W., 33 lks. dist. mkd. ¼ S32 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19492=93)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
T23S R6W
¼
S32 | S33
1994

from which bearing trees mkd. by Gould, Gawron, and Eggen
A fir, 18 ins. diam., bears N. 5° E., 77 lks. dist., with healed blaze.
A hemlock, 10 ins. diam., bears N. 44¼° E., 61 lks. dist., with healed blaze.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the ¼ sec. cor. of secs. 32 and 33, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N. 27° 37' 00" E., 0.826 chs. dist.; monumented with an iron post, 2 ins. diam., firmly set, projecting 8 ins. above the ground, in a collar of stone, with brass cap marked and witnessed as described in the official record, except the SE. bearing tree is a hemlock, bears S. 8¼° E. (record, fir, S. 9 3/4° E.), and the NW. bearing tree bears N. 82 3/4° W., 32 lks. dist. (record, N. 83½° W., 33 lks.) Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.

Robert Ward - Ron Rice & Josh Reed, crew - June 2010 - C.S.
File 65/69-28

Found - BLM Brass Cap (properly marked) dated 1994 with the following Accessories;
18" Fir Bears N.5°E., 50.8' healed face
10" Hemlock now blow down
Fd Gould, Gawron & Eggen corner as reported by BLM
New - 35" Fir Bears S.15°E., 29.7' scribed "¼ S33 BT"
32" Fir Bears N.64°W., 17.9' scribed "¼ S32 BT"
Compass Declination: 17½°E