

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2431)

-----  
A Cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on W. face, from which  
A Fir 8" dia., bears N.55°E., 138 lks. dist. mkd. ¼ S BT.  
A Fir 15" dia., bears N.60°W., 88 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12692)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 30" long, 2" dia., 20" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:  
T23SR6W  
¼  
S29 S28  
1957

from which  
A Fir 15" dia., bears N.88°E., 26 lks. dist. mkd. ¼ S28 BT  
A Fir 27" dia., bears S.45°W., 28 lks. dist. mkd. ¼ S29 BT

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19495)

-----  
Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner.  
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T23S R6W  
¼  
S29 S28  
1994

from which bearing trees mkd. in 1986 under this group  
A fir, 33 ins. diam., bears S. 68½° W., 50 lks. dist., mkd. ¼ S29 BT. (In 1994 this is a healed blaze.)  
A fir, 23 ins. diam., bears N. 16½° W., 16 lks. dist., mkd. ¼ S28 BT. (In 1994 this is a healed blaze.)  
Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, the  $\frac{1}{4}$  sec. cor. of secs. 28 and 29, erroneously reestablished by Gould, Gawron, and Eggen in 1943-1957, bears S.  $34^{\circ} 22' 30''$  W., 3.183 chs. dist.; monumented with an iron post,  $2\frac{1}{2}$  ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the bearing trees.