

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2431)

-----  
Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 20, 21, 28 and 29, mkd. T23S S21 on NE.; R6W S28 on SE.; S29 on SW. and S20 on NW. faces, from which  
A Fir 6" dia., bears N.57°E., 33 lks. dist. mkd. T23S R6W S21 BT.  
A Fir 8" dia., bears S.10°E., 125 lks. dist. mkd. T23S R6W S28 BT.  
A Laurel 6" dia., bears S.35°W., 33 lks. dist. mkd. T23S R6W S29 BT.  
A Fir 8" dia., bears N.45°W., 160 lks. dist. mkd. T23S R6W S20 BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12693)

-----  
Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 30" long, 2" dia., 20" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:  
T23SR6W  
S20 S21  
S29 S28  
1957

from which  
A Fir 37" dia., bears N.79°E., 86 lks. dist. mkd. T23S R6W S21 BT.  
A Fir 28" dia., bears S.44 3/4°E., 91 lks. dist. mkd. T23S R6W S28 BT.  
A Fir 27" dia., bears S.70°W., 17 lks. dist. mkd. T23S R6W S29 BT.  
A Fir 12" dia., bears N.12 3/4°W., 31 lks. dist. mkd. T23S R6W S20 BT.

BLM Resurvey - James E Jelley, Wayne L. Rogers, and Lance J. Bishop, Cadastral Surveyors Under Group # 1098 - Surveyed June 1982/Nov. 1983 (DCSO records Vol. 46 Page(s) 17725-26)

-----  
The Sec. cor., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with 1957 brass cap from which the remains of bearing trees mkd. by Gould, Gawron and Eggen  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A Fir 41" dia., bears N.79°E., 86 lks. dist. with healed blaze.  
A Fir snag 25" dia., bears S.70°W., 17 lks. dist., with healed blaze.  
A Fir 17" dia., bears N.11½°W., 49 lks. dist., with healed blaze. (Rec. N.12 3/4°W. 31 lks.)  
and new bearing trees  
A Fir 10" dia., bears S.10½°E., 121 lks. dist. mkd. T23S R6W S28 BT.  
A Fir 6" dia., bears S.81¼°W., 121 lks. dist. mkd. T23S R6W S29 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19495-96)

-----  
Point for the cor. of secs. 20, 21, 28, and 29, at proportionate distance. There is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T23S R6W  
S20 S21  
S29 S28  
1994

from which bearing trees mkd. by Gould, Gawron, and Eggen  
A fir, 42 ins. diam., bears N. 67° E., 28 lks. dist., with healed blaze.

A fir, 20 ins. diam., bears N. 58 3/4° W., 80 lks. dist., with healed blaze.

and a bearing tree mkd. by Jelley, Rogers, and Bishop  
A fir, 9 ins. diam., bears S. 81½° W., 180 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

and a new bearing tree  
A fir, 26 ins. diam., bears S. 35½° E., 78 lks. dist., mkd. T23S R6W S28 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the cor. of secs. 20, 21, 28, and 29, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears S. 83° 37' 00" W., 0.585 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap marked and  
(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

witnessed as described in the official record, except the SW. bearing tree mkd. by Gould, Gawron, and Eggen is dead and down, and the SE. bearing tree mkd. by Jelley, Rogers, and Bishop is a snag. Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the SW. dead and down tree and the SE. snag.