

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2434)

Set Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on W. face, from which
A Fir 6" dia., bears N.20°E., 32 lks. dist. mkd. ¼ S BT.
A Fir 8" dia., bears S.16°W., 21 lks. dist. mkd. ¼ S BT.

Survey by Wilford N. Haines and Leo J. Martin - For: Harold Woolley and E.G. Whipple, Yoncalla Lumber Co. - April 1957 RM 1-17 (and Haines Field Books, H-226 & H-227)

Set 1" x 36" Angle iron with brass cap.
BTs - 20" Hemlock S.50°E., 55.0 ft.
20" Fir N.69°W., 63.5 ft.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12696-97)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:
T23SR6W
¼
S17|S16
1957
from which
A Cedar 18" dia., bears S.83°E., 32 lks. mkd. ¼ S16 BT.
A Cedar 18" dia., bears S.23°W., 39 lks. mkd. ¼ S17 BT.

BLM resurvey by Joel R Herzberg, Cadastral Surveyor under Group No. 2778 - surveyed May 2015/July 2016 - (DCSO records Vol. 59 Page(s) 23553-4)

Point for the ¼ sec. cor. of secs. 16 & 17, at proportionate; there is no remaining evidence of the original cor.
Set a stainless steel post, 28" long, 2½" dia., 25" in the ground, with brass cap mkd.
T23S R6W
¼ S17|S16
2016
from which
A fir, 25" dia., bears N.73°E., 17.7 ft., mkd. ¼ S16 BT.
A hemlock, 11" dia., bears N.46°W., 44.8 ft., mkd ¼ S17 BT
Corner is located on a steep NE. facing slope in an area that has visibly subsided. continued next page

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this cor., a point erroneously reestablished for the ¼ sec. cor. of secs. 16 & 17, by Haines, in 1957, bears N.3°12'01"E. 1.50 ft., found disturbed, lying horizontal, 10" below the surface of the ground, and was not accepted for the cor., and was re-set to now function as a reference monument, monumented with a "T" iron, 3/4" dia., firmly set, flush with the surface of the ground, with a brass washer mkd. WILFORD N HAINES 239 SURVEY POINT DRAIN ORE.