

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2430)

Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which
A Yew 8" dia., bears N.21°E., 33 lks. dist. mkd. ¼ S BT.
A Hemlock 10" dia., bears S.63°W., 52 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12691)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 22" in the ground, with brass cap mkd:
T23SR6W
¼ S 28
S 33
1957

from which
A Fir 28" dia., bears N.74°W., 88 lks. dist. mkd. ¼ S28 BT
A Fir 26" dia., bears S.69°E., 123 lks. dist. mkd. ¼ S33 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19494)

Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
T23S R6W
S28
¼
S33
1994

from which bearing trees mkd. by Gould, Gawron, and Eggen
A fir, 38 ins. diam., bears S. 66½° E., 126 lks. dist., with healed blaze.
A fir, 40 ins. diam., bears N. 79½° W., 93 lks. dist., with healed blaze.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the $\frac{1}{4}$ sec. cor. of secs. 28 and 33, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears S. $45^{\circ} 28' 30''$ W., 0.086 chs. dist.; monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap marked and witnessed as described in the official record, except the SE. bearing tree is 130 lks. dist. (record, 123 lks.), and the NW. bearing tree is 90 lks. dist. (record, 88 lks.) Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.