

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2418-19)

-----  
Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which  
A Fir 30" dia., bears S.10°E., 21 lks. dist. mkd. ¼ S BT.  
A Fir 8" dia., bears N.28°W., 14 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12680)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 30" long, 2" dia., 26" in the ground, with brass cap mkd:  
T23SR6W  
¼  
S33 S34  
1957

from which  
A Fir 14" dia., bears N.23°E., 23 lks. dist. mkd. ¼ S34 BT  
A Fir 14" dia., bears N.21°W., 21 lks. dist. mkd. ¼ S33 BT

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19483)

-----  
Point for the ¼ sec. cor. proportionate distance. There is no remaining evidence of the original corner.  
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.

T23S R6W  
¼  
S33 S34  
1994

from which a bearing tree mkd. by Gould, Gawron, and Eggen  
A fir, 26 ins. diam., bears N. 15 ¾° W., 36 lks. dist., with healed blaze.  
and a bearing object mkd. by person(s) unknown  
An X chiselled in the NE. corner of sandstone boulder, 13 x 6 x 3 ft. above the ground, bears N. 64° W., 7 lks. dist.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the  $\frac{1}{4}$  sec. cor. of secs. 33 and 34, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N.  $6^{\circ} 54' 00''$  W., 0.158 chs. dist.; monumented with an iron post,  $2\frac{1}{2}$  ins. diam., loosely set, projecting 12 ins. above a mound of stone, 3 ft. base, with brass cap marked and witnessed as described in the official record, except the NE. bearing tree is now a sawed stump. Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the stump.