

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2420)

Set Yew post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. side, from which
A Maple 6" dia., bears N.21°W., 55 lks. dist. mkd. 1/4 S BT
A Maple 6" dia., bears N.33°E., 67 lks. dist. mkd. 1/4 S BT

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12682)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd:
T23SR6W
1/4
S28 | S27
1957

from which
A Fir 9" dia., bears S.77 1/2°E., 24 lks. dist. mkd. 1/4 S27 BT
A Fir 9" dia., bears S.83°W., 102 lks. dist. mkd. 1/4 S28 BT

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19485)

Point for the 1/4 sec. cor. at proportionate distance. There is no remaining evidence of the original corner.
Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.
T23S R6W
1/4
S28 | S27
1994

from which
A fir, 17 ins. diam., bears S. 70° E., 23 lks. dist., mkd. 1/4 S27 BT.
A fir, 32 ins. diam., bears S. 83° W., 64 lks. dist., mkd. 1/4 S28 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, the ¼ sec. cor. of secs. 27 and 28, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N. 25° 26' 00" W., 0.302 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 8 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the bearing trees.