

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2420)

-----  
Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which  
A Fir 48" dia., bears S.80°W., 20 lks. dist. mkd. ¼ S BT.  
A Maple 5" dia., bears N.75°W., 32 lks. dist. mkd. ¼ S BT

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12681)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T23SR6W  
¼  $\frac{S\ 27}{S\ 34}$   
1957

from which

A Fir 22" dia., bears N.53°W., 24 lks. dist. mkd. ¼ S27 BT.

A Fir 22" dia., bears S.9°W., 13 lks. dist. mkd. ¼ S34 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19484-85)

-----  
Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T23S R6W  
S27  
¼ \_\_\_\_\_  
S34  
1994

from which a bearing tree mkd. by Gould, Gawron, and Eggen

A fir, 29 ins. diam., bears N. 22½° W., 33 lks. dist., with healed blaze.

and a new bearing tree

A fir, 7 ins. diam., bears S. 12½° E., 16 lks. dist., mkd. ¼ S34 BT.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the ¼ sec. cor. of secs. 27 and 34, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N. 16° 57' 30" E., 0.171 chs. dist.; monumented with an iron post, 2 ins. diam., firmly set, projecting 12 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted. Do not reuse the SW. bearing tree and unable to remove the marks.

Scott Toldness - Crew: Jason Raver, N Peterson, & J Rookey - Jan. 6, 2022 - C.S. File 65/109-54

-----  
Found - A 3.25" brass cap, on iron pipe, 0.1' above the ground, from which  
A 32" Fir bears Northeast, 3.0 ft dist. with healed blazes on NE face, tree was not reused by BLM in 1986-95 survey, BLM unable to remove marks.  
A 10" Fir bears S.12½°E., 10.6 ft dist. (rec. 16 lks.), with healed blazes and tag BY "PG 7/94"  
A 32" Fir bears N.22½°W., 21.8 ft dist (rec. 33 lks.) with healed blazes and tag by "PG 7/94"  
New - Replaced BT tags.  
Cleared area of debris.  
Painted BTs with a 6" band at 6' high.  
Added ferrous nails at side center of BTs.  
Compass Declination 14½°E