

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2425)

-----  
Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which  
A Cedar 10" dia., bears N.34°E., 100 lks. dist. mkd. ¼ S BT.  
A Chinquapin 10" dia., bears S.12°W., 95 lks. dist., mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12687)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post 3 ft. long, 2" dia., 30" in the ground, with brass cap mkd:  
T23SR6W  
¼  $\frac{S\ 10}{S\ 15}$   
1957

from which  
A Fir 7" dia., bears N.18½°W., 32 lks. dist. mkd. ¼ S10 BT.  
A Hemlock 6" dia., bears S.65½°E., 41 lks. dist. mkd. ¼ S15 BT.

Survey by Ken Hoffine, Wit: Gary Angiolet - For: Lone Rock Timber Co. - 6/1992 - C.S. 63/138-19 & 2/1993 C.S. 63/149-8

-----  
Found - 1957 BLM brass cap in good condition.  
Root hole bearing N.18°W., 21.0 ft. (1957 BT)  
Rotten remnants of down log with partial scribe of a "4" in burned face, bears S.65°E., 25 ft. (Rec. S.65½°E., 27.1 ft.)  
New BTs -11" D.Fir bears N.35°W., 22.4 ft. I scribe, paint, tag and put PK nail in face.  
15" D.Fir bears S.30°W., 27.9 ft. I scribe, paint, tag and put PK nail in face.  
12" Hemlock bears S.40°E., 12.0 ft. I tag.  
Corner sets in stand of young trees approx. 600 ft. East of Andrew Creek Road at North end of new BLM clear cut.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and Used in BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19492)

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22852)

-----  
The ¼ sec. cor. of secs. 10 & 15, perpetuated by Hoffine, in 1992, monumented with an iron post, 2" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd. from which bearing trees mkd. by Hoffine

A fir, 21" dia., bears S.30°W., 27.7 ft., with a healed blaze.

A fir, 20" dia., bears N.32¾°W., 22.4 ft., with a healed blaze.

and a reference tree reported by Hoffine

A hemlock, 15" dia., bears S.41°E., 12.0 ft., with a metal tag.

Corner is located 45 ft. W. of the top of a gradual spur, slopes N.20°W., and 350 ft. W. of a gravel road, 15 ft. wide, bears N.10°E. and S.10°W.