

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 2 & 3, T24-6

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2388)

-
- Set post cor. to secs. 2, 3, 34 and 35, from which
- A Fir 30" dia., bears N.12°E., 31 lks.
 - A Fir 15" dia., bears N.35°W., 23 lks.
 - A Fir 24" dia., bears S.25°W., 18 lks.
 - A Fir 24" dia., bears S.27°E., 21 lks.

GLO resurvey by William Whipple, Deputy Surveyor under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3175)

-
- The Sec. cor., post gone; reestablished same by setting cedar post 4 ft. long, 4" sq., 24" in the grund for cor. to secs. 2, 3, 34 and 35, marked T23S S35 on NE.; T24S S2 on SE.; R6W S3 on SW.; and S34 on NW. faces, with 6 notches on the South and 2 notches on the East edges, from which
- A Fir 30" dia., bears N.12°E., 31 lks. dist., mkd. T23S R6W S35 BT.
 - A Fir 24" dia., bears S.27°E., 21 lks. dist., mkd. T24S R6W S2 BT.
 - A Fir 24" dia., bears S.25°W., 18 lks. dist., mkd. T24S R6W S3 BT.
 - A Fir 15" dia., bears N.33°W., 23 lks. dist., mkd. T23S R6W S34 BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12643-44)

-
- The Sec. cor., a wooden stake, 30" long, 6" sq., firmly set, with scribe marks rotted off, and remains of the original bearing trees:
- A dead and fallen Fir 30" dia., bears N.12°E., 31 lks. marks rotted off.
 - A dead and fallen Fir 24" dia., bears S.27°E., 21 lks. dist., marks rotted off.
 - A dead and fallen Fir 24" dia., bears S.25°W., 18 lks. dist., mkd. BT.
 - A dead and fallen Fir 15" dia., bears N.33°W., 23 lks. dist., mkd. rotted off.

At the corner point
Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 34; 3 & 2, T24-6

Alias	Description
Alias	Description
Alias	Description
Alias	Description

T23SR6W
S34|S35
S 3|S 2
T24S
1943

from which

- A Cedar 16" dia., bears N.57½°E., 33 lks. dist., mkd. T23S R6W S35 BT.
- A Fir 40" dia., bears S.30½°E., 66 lks. dist., mkd. T24S R6W S2 BT.
- A Fir 60" dia., bears S.45°W., 69 lks. dist., mkd. T24S R6W S3 BT.
- A Cedar 40" dia., bears N.57½°W., 42 lks. dist., mkd. T23S R6W S34 BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, G. Commons, crew - March 15, 1973 - C.S. File 56/25

Found - 1943 GLO brass cap at sec. corner.
28" D.Fir, now stump, N.48°W., 18.1 ft. opened for scribe S34.

This is orig. tree possibly moved
42" D.Fir, stump, (out of place) S.32°E., shows good scar.

- New BTs -14" W.Fir S.73°E., 100.5 ft. scribed T24S R6W S2 CS BT.
- 8" W.Fir N.57°E., 24.0 ft. scribed T23S R6W S35.
- 18" Cedar N.22°W., 26.8 ft. scribed T23S R6W S34 CS BT.
- 12" W.Fir S.81°W., 84.6 ft. scribed T24S R6W S3 CS BT.

Brass cap was set almost flush with surface of ground. Logging has really moved things around. Call of 1.22 chains to the West hits good. Also is good on N-S and E-W blazed lines.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22831)

The cor. of secs. 2, 3, 34, & 35, on the S. bdy. of the Tp., perpetuated by the Douglas County Surveyor's Office in 1973, monumented with an iron post, 2" dia., firmly set, projecting 1" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree

- A decayed fir snag, size indeterminate, bears N.46¾°W., 17.8 ft., with scribe mark S visible on an opened blaze. (Record, N.33°W., 15.2 ft.)

CONTINUED

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 2 & 3, T24-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of BTs mkd. by Gould, Gawron, and Eggen
A roothole bears S.30½°E., 43.6 ft., alongside of which is an uprooted, sawed, decayed fir stump, size indeterminate, with scribe marks R6W visible on an open blaze.
A sawed, decayed fir stump, size indeterminate, bears S.45°W., 45.5 ft., with no marks visible.
A roothole bears N.57½°W., 27.7 ft., alongside of which is an uprooted, sawed, decayed cedar stump, size indeterminate, with no marks visible.
and BTs mkd. by the Douglas County Surveyor's Office
A fir, 30" dia., bears N.56¾°E., 24.0 ft., with a healed blaze.
A fir, 37" dia., bears S.72°E., 99.0 ft., with a healed blaze.
A fir, 33" dia., bears S.80¾°W., 84.5 ft., with a healed blaze.
A cedar, 39" dia., bears N.22½°W., 26.7 ft., with a healed blaze.
Corner is located 70 ft. S. of a gravel road, 11 ft. wide, bears N.85°W. and S.85°E., and 195 ft. E. of the same gravel road, bears N.10°W. and S.30°E., and 2 ft. W. of a creek, 1 ft. wide, course N.45°W.