

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 500320

PRIMARY CORNER DESCRIPTION S. 1/16 cor. for Secs. 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12673)

Point for the S 1/16 sec. cor. of secs. 22 and 23.
Set an iron post, 30" long, 2" dia., 26" in the ground, with brass cap mkd:
 S 1/16
 S22 | S23
 1957

from which

 A Fir 9" dia., bears N.67½°E., 94 lks. dist., mkd. S 1/16 S23 BT.

 A Fir 12" dia., bears S.12°W., 75 lks. dist. mkd. S 1/16 S22 BT.

Douglas Co. Surveyors Office - Gary Langlitz, Deputy - James H. Cook, crew - Dec. 31, 1975 - C.S. File 57/39-52

Found - 2" I.P. firmly set. (1957 govt. resurvey)
 9" D.Fir alive with scribing visible on unhealed blaze, bears N.54°E., 62.0 ft. (Rec. N.67½°E., 62.0 ft.)
 12" D.Fir now a 5 ft. tall snag, bears S.12°W., 50.9 ft. (Rec. S.12°W., 49.5 ft.) Scribing visible.
New BT - 18" D.Fir bears N.25°W., 79.3 ft. scribed "S 1/16 S22 CS BT" on a double blaze.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/August 22, 1995 - (DCSO records Vol. 51 Page(s) 19478)

Point for the S 1/16 sec. cor. of secs. 22 and 23.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

 S 1/16
 S22 | S23
 1994

from which a bearing tree mkd. by Langlitz, in 1975,

 A fir, 18 ins. diam., bears N. 26° W., 133 lks. dist., with healed double blaze.

and a new bearing tree

 A fir, 21 ins. diam., bears N. 65½° E., 113 lks. dist., mkd. S 1/16 S23 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 500320

PRIMARY CORNER DESCRIPTION So. 1/16 cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, the S 1/16 sec. cor. of secs. 22 and 23, erroneously established by Gould, Gawron, and Eggen in 1943-57, bears N. 29° 59' 30" W., 0.142 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap marked and witnessed as described in the official record, except the NE. bearing tree is a snag, bears N. 53½° E. (record, N. 67½° E.), and the SW. bearing tree is gone. Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the bearing tree snag.