

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2413)

Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on N. face, from which
 A Fir 24" dia., bears N.10°E., 150 lks. mkd. ¼ S BT.
 A Fir 24" dia., bears S.31°E., 27 lks. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12674)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
 Set an iron post 30" long, 2" dia., 26" in the ground, with brass cap mkd.
 T23SR6W
 ¼ $\frac{S\ 14}{S\ 23}$
 1957

from which
 A Fir 20" dia., bears N.17°E., 66 lks. dist. mkd. ¼ S14 BT
 A Fir 12" dia., bears S.20°W., 30 lks. dist. mkd. ¼ S23 BT

Fd. OK, April 1993, K. Hoffine, M 117-3

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19481)

Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner.
 Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.
 T23S R6W
 S14
 ¼ -----
 S23
 1994

from which bearing trees mkd. by Gould, Gawron, and Eggen
 A fir, 28 ins. diam., bears N. 23° E., 70 lks. dist., with healed blaze.
 A fir, 32 ins. diam., bears S. 1° E., 26 lks. dist., with healed blaze.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the ¼ sec. cor. of secs. 14 and 23, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N. 86° 21' 00" E., 0.094 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 10 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22855)

The ¼ sec. cor. of secs. 14 and 23, monumented with an iron post, 2½" dia., firmly set, projecting 1" above a collar of stone, with a brass cap (properly) mkd.

from which bearing trees mkd. by Gould, Gawron, and Eggen

A fir, 30" dia., bears N.23°E., 46.2 ft., with a healed blaze.

A fir, 33" dia., bears S.1°E., 17.2 ft., with a healed blaze.

From this cor., a point erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N.86°40'46"E., 5.67 ft., monumented with an iron pipe, 2½" dia., firmly set, top 5" below ground surface.

Corner is located 150 ft. S. of a creek, 3 ft. wide, course S.30°E., and 50 ft. W. of the same creek, 3 ft. wide, course S.15°E.