

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #310, dated Nov. 30, 1878 (DCSO records Vol. 6 Page(s) 2395)

Set post, in head of timber flat, for cor. secs. 25, 26, 35 and 36, from which

- A Fir 15" dia., bears S.83½°W., 41 lks.
- A Cedar 30" dia., bears N.45 3/4°W., 64 lks.
- A Maple 6" dia., bears N.60½°E., 54 lks.
- A Fir 10" dia., bears S.47 3/4°E., 52 lks.

Cor. Fd. and used in GLO survey by John A. McQuinn, under contract #466, dated April 5, 1883 (DCSO records, Vol. 6 Pages 2397-98)

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12658-59)

The sec. cor., determined by reference to the record bearing and distance to two of the original bearing trees:

- A rotted Fir stump 10" dia., bears S.47 3/4°E., 52 lks. dist., mkd. rotted off.
- A Cedar 36" dia., bears N.45 3/4°W., 64 lks. dist., mkd. T23 with other marks grown over.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

T23SR6W
S26|S25
S35|S36
1943

from which

- A W.Fir 9" dia., bears N.86°E., 176 lks. dist., mkd. T23S R6W S25 BT.
- A W.Fir 16" dia., bears S.16°E., 85 lks. dist., mkd. T23S R6W S36 BT.
- A Fir 12" dia., bears S.66½°W., 27 lks. dist., mkd. T23S R6W S35 BT.
- A W.Fir 6" dia., bears N.79°W., 74 lks. dist., mkd. T23S R6W S26 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, L. Monrean, crew - Dec. 19, 1972 - C.S. File 49/143-102

Found - 1943 GLO brass cap in place and OK.
16" now 24" W.Fir S.16°E., 56.1 ft., alive, OK, shows scar and is tagged. (Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" now 16" D.Fir S.66½°W., 17.8 ft., now snag, 25 ft. high, shows scar. Has "W" brag mark facing corner.

No trace of OBT to NE. OBT to NW down and out of place, scribed.

New BTs -18" W.Fir S.82°W., 11.3 ft. mkd. T23S R6W S35 CS BT
13" Maple N.86½°W., 20.5 ft. mkd. T23S R6W S26 CS BT
8" W.Fir N.11°E., 21.0 ft. mkd. S25 CS BT (only)

Corner lies on moderate westerly slope, approx. 200 ft. East of logging road.

Cor. Fd. and used in BLM resurvey by Jolley, Rogers and Bishop, Cadastral surveyors, under Group #1098, surveyed June 1982/Nov. 1983 (DCSO records, Vol. 46 Pages 17727-28)

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22834)

The cor. of secs. 25, 26, 35, and 36, perpetuated by the Douglas County Surveyor's Office in 1972, monumented with an iron post, 2" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd.

from which the remains of BTs mkd. by Gould, Gawron, & Eggen

- A fir, 41" dia., bears S.16°E., 56.1 ft., with a healed blaze.
- A decayed fir stump, size indeterminate, bears S.66½°W., 17.8 ft., with no marks visible.

and BTs mkd. by the Douglas County Surveyor's Office

- A fir, 24" dia., bears N.11°E., 21.1 ft., with a healed blaze.
- A fir, 34" dia., bears S.82°W., 11.2 ft., with two healed blazes parallel to one another.
- A maple, 22" dia., bears N.86½°W., 20.5 ft., with a healed blaze.

Corner is located 125 ft. N. of a ridge, bears N.40°E. and S.40°W., and 295 ft. E. of a gravel road, 14 ft. wide, bears N.30°E. and S.30°W.

2