

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 6 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1497)

Set standard 1/4 sec. post, from which
A W.Oak 12" dia., bears S.72½°E., 400 lks. dist.
A W.Oak 20" dia., bears S.42°W., 446 lks. dist.

Volume 2 Page 265 (Surveyor, Date ??)

Set post 4x4x3 from which
W.Oak 16" bears S.7°00'W., 120 lks.
W.Oak 8" bears S.20°05'E., 197 lks.
Old marks in evidence - BTs.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C. Putnam, crew - April/May 1962 - C.S. File 52/145-3

Found - W.Oak now 27", S.7°W., 79.2 ft. Chopped open and found good scribing "S".
30" W.Oak S.20°E., 130.0 ft., shows scar.
Set Brass cap at cor. mkd: County Surveyors Office
T23S R7W ¼ S 6
1962
New BTs -20" W.Oak S.4°W., 62.3 ft. mkd. ¼ S6 CS BT.
21" D.Fir S.33°E., 59.8 ft. mkd. ¼ S6 CS BT.
Corner is in fence corner. Fences E., W., and S. from corner.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - June 30, 1987 - C.S. File 62/45-4

Found - 1962 DCSO brass cap on a 1¼" O.D. Iron pipe leaning 1.3 ft. southeast; protrudes 9" above ground.
No original BTs found. All bearings and distances taken to plumb position of brass cap/iron pipe.
16" now 29" dia. W.Oak with a previously opened blaze (no scribing found) bears S.7°W., 79.2 ft. (agrees well with rec.)
8" now 33" dia. W.Oak with a fully healed single blaze bears S.21½°E., 131.5 ft. (Rec. S.20°E., 130.0 ft. distance is a face measurement per Vol. 2 Pg. 265)
20" now 24" dia. W.Oak with a fully healed double blaze bears S.4°W., 62.3 ft. (agrees well with rec. per Godfrey)
21" now 36" dia. D.Fir with a fully healed single blaze bears S.33°E., 60.5 ft. (Rec. S.33°E., 59.8 ft. distance is a face measurement per Godfrey)

(Cont. Next Page)

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 6 only

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Douglas Co. brass cap and iron pipe returned to plumb position, protrudes 9" above ground. Monument lies at the intersection of an E-W and South running fence lines.

Fd. OK, Sept. 1992 by Beckley - M 119-80
Fd. OK, Mar. 1997 by G. Lang - M 126-67