

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 200178

PRIMARY CORNER DESCRIPTION M.C. on East bdy. Sec. 31

Alias <u>869170</u>	Description <u>M.C. right bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2489)

I set a post for cor. to fractional secs. 31 and 32 on the North side of river, from which
 An Ash 8" dia., bears S.60°W., 60 lks. dist.
 A broken Maple 36" dia., bears S.48°E., 95 lks. dist.

Douglas County Surveyors Office - Milo Godfrey and crew - C.S. File 52/125-42 - Jan. 1966

Corner searched for, not found.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1102, surveyed July/Aug. 1982 - (DCSO records Vol. 46 Page(s) 17600)

Point for the meander cor. of secs. 31 and 32, on the right bank of the Umpqua River, at proportionate distance; there is no remaining evidence of the original corner. No permanent monument established.