

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 251600

PRIMARY CORNER DESCRIPTION M.C. on South Bdy. Sec. 5

Alias <u>871080</u>	Description <u>M.C. on right bank Umpqua River</u>
Alias <u>050100</u>	Description <u>Pt. on E. bdy. DLC 50</u>
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2498)

Right bank of the Umpqua River where set post cor. to fractional secs. 5 and 8, from which
 An Oak 15" dia., bears N.15°W., 161 lks. dist.
 An Oak 10" dia., bears S.34¼°W., 383 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Dec. 1965 - C.S. File 52/125

Found - Orig. 15" now 30" Oak, N.15°W., 106.3 ft., now almost dead. BT on right bank, previously opened and shows scribe. We open and find "BT".
 No trace of SW. BT.

Since corner fits the E-W section line btwn. secs. 5 and 8, we assume a mistake in original section number, should be S5. Set Brass cap at cor. mkd:

County Surveyors Office
T 23 S R 7 W
M.S. S 5
 S 8
 1965

New BTs- 13" D.Fir S.66°W., 110.7 ft. mkd. M.C. S8 CS BT.
 6" W.Oak N.18°W., 78.5 ft. mkd. M.C. S5 CS BT.
Corner lies approx. 75.0 ft. South of road, course SW. and NE.

Fd. OK, Sept. 1992 by Beckley - M 119-80