

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 300634

PRIMARY CORNER DESCRIPTION M.C. on West bdy. Sec. 4

Alias <u>871030</u>	Description <u>M.C. on right bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2488)

To Umpqua River, set post cor. to fractional secs. 4 and 5 on right bank of river, from which
A Fir 30" dia., bears East, 20 lks. dist.
A Fir 48" dia., bears S.80°W., 55 lks. dist.

Ben B. Irving - Wit: Ray Irving; Jim Byron - Sept. 28, 1953
-C.S. File 45/211

Found original BT, 60" Fir S.80°W., 55 lks. in fair condition. Blazed and scribed two new bearing trees:
A 10" R.Fir S.68°20'W., 90.0 ft. mkd. MC S5 S4 CS BT and brass plate mkd. MC. S5 S4 T23S R7W.
A 24" R.Fir "MC S5 S4 CS BT" markings, N.10°55'E., 64.0 ft. and with brass plate mkd. MC S5 S4 T23S R7W.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Dec. 1965 - C.S. File 52/125

This corner lies on the right or North bank of river.
Found - One BT, as recorded, 24" now 27" D.Fir, N.11°E., 64.0 ft., part of brass plate and some scribe visible on partially healed face.
No trace of SW. BT.
Orig. BT, now stump.
Drive 3/4" Iron rod at corner point. Not practical to set brass cap due to possibility of high water.
New BT - 9" D.Fir N.31°W., 68.1 ft. mkd. MC S5 CS BT.