

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Standard cor. for 4 & 5 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1496)</p> <p>-----</p> <p>Set standard cor. to secs. 4 and 5, from which A B.Oak 20" dia., bears S.13°E., 143 lks. dist. A B.Oak 12" dia., bears S.46°W., 368 lks. dist.</p>
<p>John H. Markham, Jr. - Wit: Geo. &amp; Wm. Vaughn and Bob Blair -March 31, 1951 - <del>(No record source found)</del> C.S. 40/303-1 (7/3/2024)</p> <p>-----</p> <p>Determined by O.B.T., A B.Oak stump hole bears S.13°E., 94.0 ft. dist. At corner point, Set 1" x 24" Iron pipe, from which A B.Oak 7" dia., bears S.46°W., 23.0 ft. mkd. S5 BT. A Laurel 9" dia., bears N.87°E., 63.5 ft. mkd. S4 BT.</p>
<p>Pipe in N &amp; S fence, 21 ft. S. of fence cor., E., W., &amp; S., per Godfrey, 1962 - Written on previous corner renewal pgs.</p> <p>-----</p> <p>DCSO fd ok March 1, 1962 Milo Godfrey C.S. File 52/14-13 (added 3/21/2018): FD. Markham's renewal on Twp line. Fd. 1" iron pipe in N &amp; S fence line. Fd. B.Oak (now 16" dia.) S.46°W., 23.0 ft. Shows good upper scar &amp; "BT" scribed in bark below. No trace fd of orig. BTs.</p>
<p>Corey M Woodruff - For: Elkton Reserve, LLC &amp; the USA - 1/2012 - M163-30A-C</p> <p>-----</p> <p>Found - 1" IP set by Markham in fenceline BT FD - 21" Oak brs. S.46°W., 23.0' BT mkd- 18" D.Fir brs. S.16°E., 48.4'</p>
<p> </p>