

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2475)

-----  
Set ¼ sec. post, from which  
A B.Oak 15" dia., bears N.75°E., 243 lks.  
A W.Oak 8" dia., bears N.75°W., 504 lks.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #330, Surveyed Aug. 1957 (DCSO records Vol. 28 Page(s) 12095-96)

-----  
The ¼ sec. cor., monumented with the original Oak post, 27" long, 3½" square, protruding 20" above ground, marked ¼ S on SW. side, somewhat loose due to decay, but still solid, from which the remains of one of the original bearing trees:

A stump hole containing pieces of burly and decayed wood, bears N.75°E., 243 lks. dist.

At the corner point

Set an iron post, 30" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: T 23 S R 7 W

¼  
S 16 | S 15  
1957

from which new bearing trees:

A Fir 40" dia., bears S.18 3/4°E., 261 lks. dist. mkd. ¼ S15 BT. This tree is located at N. side of a trail, bears E. and W.

A double B.Oak 45" dia., bears N.82¼°W., 458 lks. dist., marked ¼ S16 BT.

The corner is located in densely growing Scotch broom, in all area which was open grassland at the time of the original survey. Reset the Oak post and an unmarked country stone, 10x10x6 ins., alongside the iron post.

Dan Baker - For: Rocking "C" Ranch - 12/2014 - M169-14

-----  
Found - 3¼" BLM Brass cap "1957"

Marked - 6" fir, N.7°E., 21.7', scribed "¼S15BT"

8" Fir, S.61°E., 20.3', scribed "¼S15BT"

8" Fir, S.15°W., 30.0', scribed "¼S16BT"

6" Fir, N.72°W., 46.5', scribed "¼S16BT"

Corner monument falls in ditch on westerly side of gravel road.