

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2473)

-----  
Set ¼ sec. post, from which  
A W.Oak 10" dia., bears S.60°E., 40 lks. dist.  
A W.Oak 6" dia., bears N.65°W., 55 lks. dist.

Ben B.Irving, Deputy Co. Surveyor - Wit: N.E. Richardson; W.E. Holcomb; Kausche - Sept. 1929 - C.S. File 37/6 and Vol. 3 Page 299

-----  
Location identified from old hub in fence corner and stump of O.B.T. as recorded in orig. field notes as N.65°W., 55 lks. bearing scribe marks.  
Set sandstone 3" x 6" x 18" long for corner, chisled X on top and ¼S on E. face; C.S. on West face.  
New BTs- 14" W.Oak bears S.85°W., 117 lks. dist. blazed and scribed ¼ S 27 CS BT.  
36" Fir bears N.70°W., 130 lks. dist., blazed and scribed ¼ S22 CS BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan. 1966 - C.S. File 52/125-37

-----  
Found - Sandstone mkd. "X" on top, "¼" on E. face and "CS" on W. face.  
14" Oak, down and rotted, S.85°W., 77.2 ft., face gone, no scribe.  
36" now 48" Fir, N.70°W., 85.8 ft., now badly rotted stump.

Set Brass cap at cor. mkd: County Surveyors Office  
T 23 S R 7 W  
¼ S 22  
S 27  
1966

Set stone alongside.  
New BT - 10" D.Fir S.82°W., 63.7 ft. mkd. ¼ S27 CS BT.  
No other tree available. Corner lies at fence corner, fences running E.; W.; and N.

Fd. and used in BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #456, Surveyed Aug 1961/Jan. 1962 (DCSO records Vol. 31 Page(s) 13076-77)

continued next page

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 7/31/2002 - C.S. File 66/34-28

-----  
Found - 1966 DCSO brass cap/iron pipe, protrudes 11" out of  
ground.

1929 stone marked "CS and +" on top is along east  
edge of BC/IP in E-W fence line.

36" now rotted D.Fir stump no marks found (rec.  
N.70°W., 85.8 ft.) 1929

10" now 21" dia., D.Fir with a fully healed double  
blaze bears S.78°W., 63.7 ft. (rec. S.82°W., 63.7  
ft.) 1966

New - 40" dia., W.Oak double blazed & scribed "¼ S27 CS  
BT" bears S.78½°E., 28.6 ft. (10" dia. W.Oak rec.  
S.60°E., 26.4 ft. OBT?)

29" dia., W.Oak double blazed & scribed "¼ S22 CS  
BT" bears N.61°E., 56.7 ft.

22" dia., D.Fir double blazed & scribed "¼ S22 CS  
BT" bears N.71½°W., 38.0 ft.

Compass decl. 17¼°E.