

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2523)

Set Fir post for ¼ sec. cor., from which
A Fir 18" dia., bears N.70°E., 46 lks. dist.
A Fir 20" dia., bears S.73°E., 66 lks. dist.

Claude Kerr, Eng. #2125 - Corner report filed March 1949 - C.S. File 40/190

Found both Fir BTs.
Set 3" x 4 ft. Fir stake for corner.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #456, Surveyed Aug 1961/Jan. 1962 (DCSO records Vol. 31 Page(s) 13074-75)

The ¼ sec. cor., determined at record bearing and distance from the original bearing trees:
A sawed Fir stump 38" dia., bears N.70°E., 46 lks. dist., with a healed blaze.
A splintered Fir snag, 62" dia., bears S.73°E., 66 lks. dist. with a healed blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:
¼ $\frac{S\ 26}{S\ 35}$
T 23 S R 7 W
1961

from which
A Fir 7" dia., bears N.26°E., 70 lks. mkd. ¼ S26 BT
A Fir 56" dia., bears S.28¼°E., 58 lks. mkd. ¼ S35 BT.

David Edwards - For: Roseburg Resources Co - 4/2006 - M150-27

Found - Brass cap
23" Fir N.25°E., 46.2' W/healed blaze.
New BT - 10" Fir S.61°W., 15.8'
6' steel post 2' West.