

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2519)

Set Fir post for the ¼ sec. cor., from which
A Fir 48" dia., bears N.46°W., 14 lks.
A Fir 48" dia., bears S.15°E., 40 lks.

Survey by Bruce A. Shaner - For: Mt. Baldy Lumber Co. - April/May 1962 - M 23-62

Found original bearing trees.
Set square wood stake, from which a
52" D.Fir bears N.46°W., 9.2 ft., bark scribes visible.
52" D.Fir bears S.15°E., 26.4 ft. scribes no longer visible.
Old cruiser marks on nearby trees.

Douglas Co. Surveyors Office - Gary L. Langlitz; P. Earle - May 2, 1974 - C.S. File 56/51-4

CORNER REPORT ONLY
Found a small, squared wood stake near two large trees which were not cut in logging operations. These trees have apparently been used as original bearing trees in the past. We find no scribing on the apparent NW. BT; an approx. 52" D.Fir snag. The apparent SE. BT, an approx. 52" D.Fir, now down, has a very clear bark scribe "¼ S BT" with the scribe pivot hole still plainly visible on some letters. Our finding of scribing on the SE. tree and no markins on the NW. tree is contrary to the information contained in Shaner's 1962 visit. It is also inconsistent with information shown on the corner renewal request card submitted on Oct. 29, 1973 by D. Burkhardt, BLM Forester who states he found good scribing "S ¼" on NW. tree. Furthermore, record bearings and distances from these apparent BTs place the corner point approx. 3 ft. NW. of the present location of the squared wood stake. This possible corner location falls on an E-W cutting line. Both apparent BTs have been tagged previously and there are several cruisers initials chopped in the apparent BTs and nearby trees. Therefore, based on the discrepancies noted concerning the markings found and not found on the NW. tree and the apparent young age of the scribe found on the SE. tree, we do not feel we have sufficient evidence to monument the corner at this time.

(Cont. Next Page)

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Bruce A. Shaner, L.S. #430 - For: International Paper Co. - Nov. 9, 1982 - C.S. File 58/229-15

Set 2" x 32" galv. Iron pipe with a 2½" brass cap marked "Shaner Engineering RLS 430 1982 T23S R7W W.M. 1/4 S24 S25", with a steel fence post alongside, and from which

A 52" D.Fir stump, orig. BT, with probable scribe "B" cut from toe of stump, bears N.46°W., 9.2 ft. Tag by Haines and BLM BT tag both on this stump. I rescribed "¼ S24 BT".

A 52" D.Fir, orig. BT, bearing S.15°E., 26.4 ft., now missing. Apparently removed by BLM land clearing operation to the South for the progeny tree orchard.

In 1962, when I was at this corner, the NW. BT had scribes visible and the SE. BT was still in position.

New BT - 36" D.Fir stump, I scribed "¼ S25 BT", bears S.79°W., 29.6 ft.

The corner is at the same location as the corner that I set a squared wood stake in 1962. The wood stake was found on the ground near the corner. There is an E-W blazed line and timber cutting line through the corner location. There is a cutting line 1/2 mile North on a bearing of N.1°W., as per 1962 survey on the N-S section centerline.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 9/11/2019 - C.S. File 65/104-4

Found - Shaner's 2" dia. iron pipe with 2½" dia. brass cap in good condition

New - A 12" dia. Fir scribed. "¼ S24 BT" bears N.12°W., 15.9'

A 16" dia. Fir scribed "¼ S25 BT" bears S.25°W., 15.0'

Note - Compass decl. 15°E.