

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO recs Vol. 6 Pages 2520-21)

Set Yew post for the 1/4 sec. cor., from which
A Fir 60" dia., bears N.10°E., 29 lks. dist.
A Fir 60" dia., bears S.30°W., 51 lks. dist.

Wilford N. Haines - For: E.G. Whipple - 5/9/1957 - M 5-20

Found original corner.
Set 1" x 1" x 36" T. Iron rod with brass cap inscribed "Survey Point Wilford N. Haines #239".

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon "Ray" Tracy, crew - July 1962 - C.S. File 52/125-5

Found - Fir now 64", S.30°W., 33.7 ft. to face, plain bark scribing visible "1/4 S BT". Tree dying.
Fir stump, now 72", N.10°E., 19.1 ft. to face, plain bark scribing visible "1/4S". Lower blaze of stump buried in dirt and debris.

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S R 7 W

1/4 $\frac{S\ 12}{S\ 13}$

1962

New BTs- 17" Yew S.68°E., 30.2 ft. mkd. 1/4 S13 CS BT.
18" Hemlock N.16°W., 57.1 ft. mkd. 1/4 S12 CS BT.
Corner lies in old cat road approx. 60 ft. West of logging road and approx. 80 ft. South of creek.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 1/30/2006 - C.S. File 67/14-4

Found - Haines T-Iron w/brass washer attached - loose on top of ground - no sign of 1962 DCSO BC/IP.
Orig. 60" fir now rotting D.Fir stump approx. 60" dia., x 4 ft. tall possible fragmentary bark scribing visible below tag, bears N.4°E., 21.1 ft. to center of stump. Agree with 19.1 ft. to face (DCSO 1962) (Rec. N.10°E., 19.1 ft) Orig. BT
Orig. 60" fir now rotting D.Fir stump approx. 55" dia., x 3 ft. tall no scribe or face visible bears S.28°W., 36.3 ft. to center of stump agree with 33.7 ft. measurement to face (DSCO 1962) (Rec. S.30°W., 33.7 ft.) Orig. BT.

continued next page

