

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated June 8, 1857 - DLC Volume, Page 138</p> <p>-----</p> <p>Set post NW. cor., from which An Oak 15" dia., bears S.17¼°E., 995 lks.</p>
<p>J.W. Cole, Deputy - Wit: Smick; Haines; Warren Cheever - Feb. 29 1921 - Vol. 3 Pages 89-90 and Field Book 20 Pg. 28</p> <p>-----</p> <p>Set this corner from tie given to section corner. Set an Iron plow coulter, also an Oak post. Marked - An Oak 24" dia., S.14 3/4°E., 104.5 ft. An Oak 24" dia., S.73°20'E., 112.5 ft.</p>
<p>Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 21, 1965 - C.S. File 52/125-28</p> <p>-----</p> <p>Found - 24" now 28" W.Oak S.73°E., 112.5 ft., open and find "C" scribe. 24" now 31" W.Oak S.14°E., 104.5 ft., shows good scar. Do not open. No trace of plow coulter set for corner monument. Set Brass cap at cor. mkd: County Surveyors Office T 23 S R 8 W _____ N.W. DLC 39 / _____ 1965</p> <p>Since BTs are alive and in good condition, we do not mark new ones. Corner lies at fence corner, course S.17°W. and S.75°E.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 6/13/2002 - C.S. File 66/34-8</p> <p>-----</p> <p>Found - 1965 DCSO brass cap iron pipe, protrudes 7" out of ground, top of cap bent 6" south west of plumb. Fence corner is 3 ft. SW of BC/IP. 24" now down, a rotted Oak bears S.73°E., 112.5 ft. (1921) 24" now 39" dia., W.Oak scar not visible, bears S.14°E., 104.5 ft. (1921)</p> <p>Reset - DCSO BC/IP straightened, set back at plumb position protrudes 5" out of ground.</p> <p>New - 20" dia., Maple double blazed &amp; scribed "NW DLC 39 CS BT" bears S.82°E., 119.7 ft. 18" dia., W.Oak double blazed &amp; scribed "NW DLC 39 CS BT" bears N.87°E., 153.7 ft. Compass decl. 17½°E.</p>