

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only (West)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2546-47)

Set sandstone 14x12x6 ins., 10" in the ground for cor. to secs. 18 & 19, marked with 3 notches on N. and S. edges, from which

- A Fir 50" dia., bears N.15°E., 28 lks. dist. mkd. T23S R8W S18 BT.
- A Cedar 20" dia., bears S.75°E., 67 lks. dist. mkd. T23S R8W S19 BT.
- A Cedar 14" dia., bears N.79°W., 15 lks. dist. mkd. T23S R8W S18 & 19 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Jan. 1967 - C.S. File 54/12-6

Found - Orig. 50" now 72" Fir N.15°E., 18.5 ft., alive, shows good scar. Do not open.
Orig. 20" now 38" Cedar S.75°E., 44.2 ft., alive, scribe visible on unhealed blaze.
Orig. 14" now 30" Cedar N.79°W., 9.9 ft., badly injured, no scribe found.

No trace of sandstone called for in notes.

Set Brass cap at cor. mkd: County Surveyors Office

R		T 23 S	R
9		<u>S 18</u>	8
W		S 19	W
		1967	

New BTs- 8" Hemlock S.59°E., 26.3 ft. mkd. T23S R8W S19 CS BT
14" Hemlock N.75°E., 30.8 ft. mkd. T23S R8W S18 CS BT.

This corner lies on steep, SW. slope, approx. 200 ft. N. of creek.

Fd. and used in BLM resurvey by James E. Jelley and Rolla R. Steward, Cadastral Surveyors under Group # 703, surveyed July 1969/May 1970 (DCSO records Vol. 35 Page(s) 14544)

Fd. and used in BLM Resurvey by Harvey E. Wofford and Stephen J. Malloy, Cadastral Surveyors, under Group #1074, Surveyed July 1980/Nov. 1982 - (DCSO records Vol. 43 Page(s) 16847)