

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 100614

PRIMARY CORNER DESCRIPTION Sec. cor. for 1 & 12 only, T23-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 279, dated March. 5, 1878 - (DCSO records Vol. 6 Page(s) 2537)

-----  
Set a Fir post 5" dia., 40" ling, 20" in ground for the corner to secs. 1, 6, 7 and 12, from which  
A Fir 8" dia., bears N.60°E., 14 lks. dist.  
A Fir 36" dia., bears S.50°E., 40 lks. dist.  
A Fir 60" dia., bears S.45°W., 9 lks. dist.  
A Fir 24" dia., bears N.20°W., 45 lks. dist.

Wm. Whipple, Contract #622, dated June 1893, called this "The old cor. to sec. 1 & 12, T23S R9W" (DCSO records, Vol. 6 Page 2549)

Douglas Co. Surveyors Office - L.E. Monrean; P.Earle, crew - Oct. 19, 1973 - C.S. File 56/39-14

-----  
Unrecorded evidence found. Corner not set  
Found - 2" sq. post out of ground with location marker tag "S B Merrick, D. Mower  $\frac{1}{12}$  8/15/57.  
6 ft. stump, uprooted and down hill from its orig. location, bears a tag mkd. "RD 5/2/67 Sadler"  
Scribed stake 2 ft. North, "H O Malac 10-15-64.  
15" Fir with Forestry appraisal tag.  
All BTs are gone or uprooted with no scribing.

BLM Resurvey by Harvey E. Wofford and Stephen J. Malloy, Cadastral Surveyors, under Group #1074, Surveyed July 1980/Nov. 1982 - (DCSO records Vol. 43 Page(s) 16849-50)

-----  
The cor. of secs. 1 and 12 only, determined from the remains of the original bearing trees:  
A roothole bears S.50°E., 40 lks. dist., alongside of which is a downed, decayed Fir, size indeterminate, no marks remaining.  
A roothole bears S.45°W., 9 lks. dist., alongside of which is Fir stump 66" dia., no marks remaining.  
A roothole bears N.20°W., 45 lks. dist., alongside of which is a downed, decayed Fir 38" dia., no marks remaining.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
T 23 S      T 23 S  
S 1      R 8 W  
S 12  
R 9 W      S 6      1980

(Cont. Next Page)

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 100614

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12 only, T23-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which new bearing trees:  
A Fir 6" dia., bears S.37 3/4°W., 15 lks. dist., mkd. T23S R9W S12 BT.  
A Hemlock 13" dia., bears N.55½°W., 88 lks. dist., mkd. T23S R9W S1 BT.  
Set a 5 ft. steel fence post alongside the iron post.

Mark Smalley - For: Riverbend Resources - Oct. 1997 - M 124-64  
-----  
Fd. - 1980 Cadastral Brass cap on Iron pipe  
BTs - 8" Fir, S.37 3/4°W., 9.9' healed.  
17" Hemlock, N.55½°W., 58.1', healed.  
New BTs -  
14" D.Fir, N.32°E., 24.4' Scribed "S6 BT"  
10" d.Fir, S.80°E., 15.8', scribed "S6 BT"