

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 2607)

-----  
A Fir 40" dia., which I mark  $\frac{1}{4}$  S on N. side for  $\frac{1}{4}$  sec. cor., from which

A Maple 14" dia., bears N.25°E., 19 lks. dist. mkd.  $\frac{1}{4}$  S BT  
A Fir 12" dia., bears S.58°W., 30 lks. dist. mkd.  $\frac{1}{4}$  S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 10, 1966 - C.S. File 54/12-36

-----  
Found - Orig. 40" now 54" D.Fir corner tree, no scribing found.

Orig. 14" now 18" Maple N.25°E., 12.5 ft., open, center rotted away, no scribing found.

Orig. 12" now 18" D.Fir S.58°W., 19.8 ft., open and find poor " $\frac{1}{4}$  S" on burned face.

Since distances E. and W. would be too large to set Wit. Cor., we run North 55.0 ft. and Set:

Set Brass cap for Wit. Cor. mkd: County Surveyors Office

T 23 S R 8 W

Wit. Cor. 55' S. to corner

$\frac{1}{4}$   $\frac{S}{S}$   
7  
18

1966

New BTs- 23" D.Fir N.76°E., 71.1 ft. mkd. W.C.  $\frac{1}{4}$  S7 CS BT.

23" D.Fir S.74 $\frac{1}{2}$ °E., 52.2 ft. mkd. W.C.  $\frac{1}{4}$  S18 CS BT.

Actual corner location and BTs will be destroyed by road construction. Witness corner lies on steep, South slope.

Fd. and used in BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #1005, surveyed July/Dec. 1980 - (DCSO records Vol. 43 Page(s) 16830-31)