

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2603)

-----  
Set a post 4 ft. long, 4" sq., 2 ft. in ground for cor. to secs. 17, 18, 19 and 20, marked T23S S17 on NE.; R8W S20 on SE.; and S19 on SW.; and S18 on NW. faces, with 2 notches on S. and 5 notches on E. edges, from which  
A Hemlock 24" dia., bears N.4°E., 13 lks. dist. mkd. T23S R8W S17 BT.  
A Hemlock 18" dia., bears S.76°E., 22 lks. dist. mkd. T23S R8W S20 BT.  
A Maple 16" dia., bears S.13°W., 44 lks. dist. mkd. T23S R8W S19 BT.  
A Hemlock 24" dia., bears N.22°W., 48 lks. dist. mkd. T23S R8W S18 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 1965 - C.S. File 54/12-33

-----  
Found - 4" square post at corner.  
Orig. 24" now 26" Hemlock N.4°E., 8.6 ft., laying face down.  
Orig. 18" now 28" Hemlock S.76°E., 14.5 ft., open, face badly rotted.  
Orig. 16" now 24" Maple S.13°W., 29.0 ft., shows good scar. Did not open.  
Orig. 24" now 31" Hemlock N.22°W., 31.7 ft., open and shows "W" scribe. This BT burned at base.

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S R 8 W  
S 18 | S 17  
S 19 | S 20  
1965

New BTs- 15" Hemlock N.25°W., 33.0 ft. mkd. T23S R8W S18 CS BT.  
20" Cedar N.81°E., 11.5 ft. mkd. T23S R8W S17 CS BT (Old BT) 28" Hemlock S.76°E., 14.5 ft. mkd. T23S R8W S20 CS BT.

Corner lies in bottom of small ravine, course South.

Douglas Co. Surveyors Office - John M. Powell, Gary L. Langlitz, crew - Aug. 3, 1972 - C.S. File 54/12-70

-----  
Found - Orig. Hemlock now 10 ft. stump, N.22°W., 31.2 ft. Faint scribe visible "S18"

(Cont. Next Page)

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

28" Hemlock now 7 ft. stump S.76°E., 14.5 ft. Scribe visible "T23S R8W S20 CS BT"  
20" Cedar, uprooted stump lying on face with Tracy's BT tag.  
No trace of 1965 brass cap. Area badly torn up from logging. Other BTs destroyed.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 23 S R 8 W  
S 18 | S 17  
S 19 | S 20  
1972

Also steel fence post along side.  
New BTs- 52" Fir stump S.49°W., 45.5 ft.  
30" Cedar stump S.37°E., 43.7 ft.  
Corner lies on old clear cut. No trees available for BTs.