

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2554)

Set a post 4 ft. long, 4" sq., 2 ft. in ground for cor. to secs. 33 and 34, about 200 ft. below top of last spur, marked T23S R8W on N.; S34 on E.; and S33 on W. faces, with 3 notches on E. and W. edges, from which
A Fir 60" dia., bears N.83°E., 29 lks. dist. mkd. T23S R8W S34 BT.
A Fir 12" dia., bears N.79°W., 63 lks. dist. mkd. T23S R8W S33 BT.
A Fir 40" dia., bears S.67°W., 62 lks. dist. mkd. T23S R8W S33 & 34 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan. 1967 - C.S. File 54/12-23

Found - Orig. 60" now 62" Fir, N.83°E., 19.1 ft., alive, shows "T W" & fragmentary bark scribe.
Orig. 40" now 43" Fir, S.67°W., 40.9 ft., alive, shows good scar. We do not open.
Orig. 12" Fir now 16" decayed remains of stump, N.79°W., 41.6 ft., find "BT"
Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
S 33 | S 34
T24S
New BTs- 16" D.Fir N.34½°E., 22.7 ft. mkd. T23S R8W S34 CSBT
12" D.Fir N.37°W., 25.2 ft. mkd. T23S R8W S33 CS BT
Corner lies on steep South slope approx. 40 ft. West of shallow draw, course SW.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Karen Reed; John Powell, crew - Oct. 13, 1982 - C.S. File 62/1-23

Found - Area completely covered by fill from new road construction.
Orig. 40" Fir now 45", alive, with well healed blaze.
Orig. 60" Fir now 45" stump with no visible bark scribing remaining.
16" Fir now 15" stump with good scar.
Using record distances from the two remaining orig. BTs and near record dist. from the one remaining 1967 BT, I set a 1" x 30" Iron pipe with brass cap attached mkd:
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only, (South)

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

"Douglas Co Surveyor T23S S33 S34 R8W 1982" for the sec. cor. to secs. 33 & 34 only. Corner falls on a steep rocky road fill approx. 47 ft. (slope dist) South of a new road. Brg. & Dists. to found BTs are:
60" now 45" Fir, stump, bears N.85°E., 19.1 ft. (Rec. N.83°E.)
40" now 45" Fir, alive, bears S.63°W., 40.9 ft. (Rec. S.67°W.)
16" now 15" Fir stump, bears N.38°E., 22.9 ft. (Rec.N.34½°E., 22.7 ft.)
New BT - 36" Fir scribed "T24S R8W S3 CS BT" in single blaze bears S.86°W., 46.8 ft.
Douglas County Surveyor Office BT tags on all trees.

Ronald L. Rice, Ward NW - For: Roseburg Resources Co. - 5/2008 - M 156-12

Found - 2½" brass cap lying on ground out of position. BTs in evidence.

Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda - 6/18/2008 - C.S. File 67/25-61

Found - No evidence of orig. or 1967 monument fd. From 1982 renewal a 2½" dia., brass cap (properly mkd) on a 1¼" O.D. x 30" long iron pipe is fd loose on surface of ground.
A fir 60" dia., now 45" dia., 5 ft. tall D.Fir stump with no visible blaze scars & topped with a galvanized metal cap, bears N.83°E., 19.1 ft. (as per record, 1982 bearing of N.85°E., is also reasonable on this large tree) OBT
A fir 40" dia., now a 50" DBH D.Fir with possible healed single blaze (not clear) bears S.63°W., 40.9 ft. (as per 1982 rec. orig. record S.67°W., 40.9 ft.) OBT
A 16" dia., fir now 15" dia., 2½ ft. tall D.Fir stump with a fully healed double blaze, bears N.38°E., 22.9 ft. (As per 1982 renewal, 1967 rec, N.34½°E., 22.7 ft) 1967
A 36" dia., fir now 42" dia., 2½ ft. tall D.Fir stump with possible evidence of bottom of healed single blaze, bears S.86°W., 46.8 ft. (as per rec.) 1982
New - Monument position is determined from 4 agreeing dists & 2 agreeing bearings (as previously described) This position is referenced out, a hole is dug & the monument is reset in ground. cont next pg

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

| |
|--|
| <p>Monument now is firmly set & protrudes approx. 4" above ground. "RESET 2008" is added to the BC. 6" dia., D.Fir double blazed & scribed "T23S R8W S34 CS BT" bears N.40½°E., 14.6 ft.</p> <p>Note - Monument is on steep fill slope just south of NW running logging Rd. Compass decl. 16¼°E.</p> |
| <p>Ronald L Rice - For: Rome Creek Timber 1 LLC - 6/2016 - M172-20 -----</p> <p>Found - Douglas Co. brass cap mkd RESET 2008, with the following accessories: 45"x5' tall D.Fir stump with metal cap bears N.83°E., 19.1'. 50" D.Fir bears S.63°W., 40.9', axe work visible. 15" D.Fir stump bears N.38°E., 22.9', healed face. 42" D.Fir stump bears S.86°W., 46.8', axe work visible. 7" D.Fir bears N.40½°E., 14.6', scribing visible. Steel post adjacent to corner.</p> |
| <p>Ron Quimby - For: Roseburg Resources Co. - 4/2018 - M174-23 -----</p> <p>Found - Brass cap 20" 45"x5' tall fir stump w/galvanized metal cap bears N.83°E., 19.1' - no visible scribe 15"x4' tall fir stump bears N.38°E., 22.9' - healed face 8" fir bears N.40°E., 14.6' - healed face 50" fir bears S.63°W., 40.9' - axe work visible 42" fir stump bears S.86°W., 46.8' - axe work visible 6' steel post bears north 1.0'</p> <p>New - 6" fir bears N.67°W., 12.2' scribed "T23S R8W S33 BT" 6' steel post bears EAST 1.0'</p> |
| |