

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2582)

-----  
Set a post 3 ft. long, 3" sq., for ¼ sec. cor. mkd. ¼ S on North face, from which  
A Cedar 24" dia., bears S.5°W., 25 lks. dist. mkd. ¼ S BT  
A Fir 40" dia., bears N.5°W., 43 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
March 1967 - C.S. File 54/12-62

-----  
Found - Orig. 24" now 48" Cedar, alive, badly injured on W. side, S.5°W., 16.5 ft., "¼" scribe visible on badly decayed blaze.  
Orig. 40" now 54" Fir, alive, poor condition, N.5°W., 28.4 ft., shows "¼S" bark scribe in poor condition and BT scar.

Set Brass cap at cor. mkd: County Surveyors Office  
T 23 S R 8 W  
¼  $\frac{S}{S} \frac{10}{15}$   
1967

New BTs- 12" Hemlock N.61°W., 27.7 ft. mkd. ¼ S10 CS BT.  
14" Hemlock S.49°W., 15.2 ft. mkd. ¼ S15 CS BT.  
Corner lies on moderate, changing to steep, NE. slope, approx. 100 ft. W. of creek, course NE.