

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2564)

Set a sandstone 14x12x10 ins., 10" in the ground for cor. to secs. 26, 27, 34 and 35, with 1 notch on S. and 2 notches on E. edges, from which

- A Cedar 20" dia., bears N.43°E., 14 lks. dist. mkd. T23S R8W S26 BT.
- A Fir 36" dia., bears S.36°E., 85 lks. dist. mkd. T23S R8W S35 BT.
- A Hemlock 40" dia., bears S.36°W., 17 lks. dist. mkd. T23S R8W S34 BT.
- A Dogwood 6" dia., bears N.53°W., 119 lks. dist. mkd. T23S R8W S27 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffell, crew - Jan. 22, 1964 - C.S. 49/49-12

Found - Rock (sandstone) approx. 14" x 12" x 10" with "X" on top.
 54" Red Cedar N.43°E., 9.2 ft., to old face. Did not open.
 Rotted remains of Hemlock stump S.36°W., 11.2 ft.
 No trace of SE. or NW. bearing trees.

Set Brass cap alongside rock mkd: County Surveyors Office

T 23	S R 8 W
S 27	S 26
S 34	S 35
1964	

Blaze and rescribe

- 54" Red Cedar N.43°E., 9.2 ft. to old face, mkd. "T23S R8W S26 CS BT"
- New BTs- 16" R.Cedar S.16°E., 24.0 ft. mkd. T23S R8W S35 CSBT
- 62" R.Cedar S.24°W., 46.0 ft. mkd. T23S R8W S34 CSBT

No suitable trees near NW. of corner.
 Corner lies on steep N. slope approx. 60 ft. South of Waggoner Creek.

Fd. and used in BLM Resurvey by Stephen J. Malloy, Cadastral Surveyor, under Group #1219, Surveyed July/Aug. 1984 - (DCSO records Vol. 47 Page(s) 18094)

Ronald L Rice - For: Oxbow Timber 1 LLC - Jan. 2015 - M169-7

Found - No monument found due to slide.
 One BT remaining all others down or lost to slide.
 continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

	<p>Reset corner monument at record bearing and distance from the one remaining tree.</p> <p>Set - 5/8"x30 rebar with 2½" aluminum cap marked T23S R8W S27 S26 S34 S35 2015 54633LS</p> <p>35" R.Cedar bears S.16°E., 24.0' - healed face RM 1 set 2" aluminum cap on 5/8" x 30" rebar bears N.45°11'28"W., 105.77' - mkd "RM1 2015 54633LS" RM 2 set 2" aluminum cap on 5/18"x30" rebar bears S.22°54'07"W., 44.16' - mkd "RM2 2015 54633LS"</p>
	<p>Ron Quimby - For: Roseburg Resources Co - 4/2018 - M174-23 -----</p> <p>Found - 5/8" iron rod w/aluminum cap per M169-7 35" cedar bears S.16°E., 24.0' 5/8" iron rod w/2" aluminum cap stamped "RM1" bears N.45°W., 105.8' 5/8" Iron rod w/2" aluminum cap stamped "RM2" bears S.23°W., 44.8'</p> <p>New - 5/8"x30" iron rod w/2" aluminum cap stamped "RM LS 1654" bears N.19°28'54"E., 134.89'</p>