

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 10 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2572)

Set a post 3 ft. long, 3" sq., mkd. ¼ S on W. face for ¼ sec. corner, from which
A Cedar 12" dia., bears S.78°E., 86 lks. dist. mkd. ¼ S BT
A Fir 30" dia., bears N.76°W., 56 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan/Feb. 1967 - C.S. File 54/12-56

Found - Orig. 12" Cedar S.78°E., 57.4 ft., alive, shows old scars, we open and find edges of old axe blaze and fragmentary scribe marks.
Orig. 30" Fir, now turned out and badly decayed N.76°W., 37.0 ft., no scribe found.
Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
¼ S10|S11
1967
New BTs- 7" Cedar S.46°W., 44.2 ft. mkd. ¼ S10 CS BT.
20" Cedar S.52°E., 22.3 ft. mkd. ¼ S11 CS BT.
Corner lies 66 ft. N. of small creek, course SW. and on SE. slope of point of spur ridge.

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #640, surveyed July 1967/April 1968 (DCSO records Vol. 35 Page(s) 14436)

The ¼ sec. cor. of sec. 10 only, perpetuated and recorded by Tracy in 1967, monumented with an iron post 1½" dia., firmly set, projecting 8" above ground, with brass cap as mkd. in 1967, from which the original bearing trees
A Cedar 25" dia., bears S.78°E., 86 lks. dist., with fragmentary scribe marks visible on opened and rotted blaze.
A root hole bears N.76°W., 56 lks. dist., alongside of which is a down Fir, 36" dia., no marks visible.
and bearing trees mkd. by Tracy
A Cedar 23" dia., bears S.52°E., 34 lks. dist. with scribe marks ¼ S11 CS BT visible on open blaze.
A Cedar 6" dia., bears S.45°W., 67 lks. dist., with scribe marks ¼ S10 CS BT visible on opened blaze.
Add marks BLM 1967 to brass cap.

continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 10 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 4/23/2003 - C.S. File 66/58-7

Found - 1967 DCSO brass cap/iron pipe, protrudes 2" out of
ground.

12" now 26" dia., cedar previously opened no marks
visible bears S.78°E., 57.4 ft. (OBT)

Orig. NW BT now root hole.

7" now 10" dia., 4 ft. high partially rotted tipped
out stump with a healed blaze bears S.46°W., 44.2
ft. (1967)

20" now 35" dia., cedar with a fully healed blaze,
bears S.52°E., 22.3 ft. (1967)

New - 5" dia., D.Fir double blazed & scribed "¼ S10 CS BT"
bears S.67°W., 2.3 ft.

7" dia., D.Fir double blazed & scribed "¼ S10 CS BT"
bears N.4°W., 12.1 ft.