

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 35 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2553)

-----  
 Set a post 3 ft. long, and 3" sq., for ¼ sec. corner marked ¼ S. on N. face, from which  
     A Fir 30" dia., bears N.71°W., 14 lks. dist. mkd. ¼ S BT  
     A Fir 50" dia., bears S.45½°W., 46 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Feb. 1967 - C.S. File 54/12-13

-----  
 Found - Orig. 40" now 46" Fir, N.71°W., 9.2 ft., now badly decayed snag. We open and find "¼S" scribe.  
           Orig. SW. BT, down and rolled out of place.  
 Set brass cap at cor. mkd: County Surveyors Office 1967  
                                     ¼   S 35        T 23 S  
   T 24 S      R8W  
 New BTs- 11" Hemlock, N.38½°W., 21.6 ft. mkd. ¼ S35 CS BT.  
           15" D.Fir N.30°E., 21.2 ft. mkd. ¼ S35 CS BT.  
 Corner lies on gentle northerly slope of spur ridge, approx. 215.0 ft. East of ¼ S2, T24-8.

BLM Resurvey by Stephen J. Malloy, Cadastral Surveyor, under Group #1219, Surveyed July/Aug. 1984 - (DCSO records Vol. 47 Page(s) 18095)

-----  
 The ¼ sec. cor. of sec. 35 only, perpetuated and recorded by Tracy in 1967, monumented with an iron post 1½" dia., firmly set, projecting 3" above ground, with brass cap mkd. in 1967, from which the remains of an original bearing tree  
     A Fir stump 46" dia., bears N.71°W., 14 lks. dist., with scribe marks ¼ S visible on open blaze.  
 and remains of bearing trees by Tracy  
     A root hole bears N.30°E., 32 lks. dist. with a down Fir alongside, 15" dia., with healed blaze.  
     A root hole bears N.30½°W., 33 lks. dist., with a down Hemlock alongside, 11" dia., with healed blaze.  
 and a new bearing tree  
     A Hemlock 6" dia., bears N.58°E., 29 lks. dist., mkd. ¼ S35 BT.  
 No other suitable trees available.  
 Corner is located in logged area, in head of ravine, drains NE.

continued next page

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 35 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22407)

-----

The ¼ sec. cor. of sec. 35 only, on the N. bdy. of the Tp., monumented with an iron post, 1½" dia., firmly set, flush with the ground, with brass cap (properly) mkd. from which the remains of an orig. bearing tree

A sawed fir stump, 26" dia., bears N.71°W., 9.2 ft., with no marks visible.

and remains of bearing trees mkd. by the Douglas County Surveyors Office in 1967, reported by Malloy

A roothole bears N.20°E., 21.1 ft., with fallen fir trunk, 16" dia., lying alongside, with a healed blaze. (Record, N.30°E.)

A roothole bears N.36½°W., 21.8 ft., with fallen hemlock trunk, 11" dia., lying alongside, with a healed blaze. (Record, N.30½°W.)

and bearing tree mkd. by Malloy

A hemlock, 12" dia., bears N.58°E., 19.1 ft., with scribe marks ¼ S35 visible on a partially healed blaze.

and new bearing tree

A fir, 8" dia., bears N.23½°E., 5.5 ft., mkd. ¼ S35 BT.

Fd ok 5/2019, R Quimby C.S. File 65/102-49